

Basic Vehicle Condition Guide

Report ID: 17,777,119


Version: 1

Created: 13 Dec 2018

Make: Model: 130 Hyundai **Body Style:** Hatchback Year: 2012 Registration: **GNQ589** Reg Expiry: 26 Sep 2019 **Odometer:** WoF Expiry: 22 Oct 2019 71,346 Kms **Good No:** 17777119 VIN: KMHDB51DMCU3961: **Next Service:** 85000 **Service History:** Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Stone chips front screen.

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

FWD.Trans fluid leak.

Interior Commen	<u>nts</u>
Seats	Good
Carpets	Good
Panels	Good
Dashboard	Good

General Comments

Left hand brake light not working.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Eddie Marsters Date: 13 Dec 2018

	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	\(\times \)		
Performance	~		
Noise	~		
Cooling System			
Coolant condition	V V		
Performance	~		
Radiator / Hoses (visual)	~		
Transmission			
Operation	~		
Noise	~		
Clutch			~
CV joints	>		
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	>		
Tyres (lowest observed tread	depth	of tyre	es)
Left front	4	4	mm
Right front	4	1	mm
Left rear	(5	mm
Right rear	4	4	mm
Spare		Yes	
Suspension			
Suspension performance	~		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater			
Operation	~		
Electrical / Accessories			
Head lights	~		
Tail lights		~	
Indicators	~		
Dashboard warning lights	~		
Wipers (front & rear)	V V V V V		
Window winder FL	~		
Window winder FR	~		
Window winder RL	~		
Window winder RR	~		
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)	~		
Number of keys	2		
Central locking	~		
Remote locking	~		
Sat. Nav. (basic test only)			~
Reversing camera			

I have read and understood this condition guide.

Name:			