

Report ID: 17,778,412 Version: 2 05 Sep 2019 Created:

Make:	Holden	Model:	Colorado	Body Style:	Utility		Pass	Fail	N/A
Year:	2011	Registration:	GEG158	Reg Expiry:	20 Dec 2019	Engine	1	<u> </u>	I
WoF Expiry:	11 Mar 2020	Odometer:	213,938 Kms	Good No:	17778412	Oil level	~		
VIN:	MMMTFS85HBH54958	Next Service:	217000 km	Service Histor	y: No	Smoke & fumes	~		
						Performance	V		
	port is not a warranty	oration is made	for ago and milaago	Parts have not	been dismonthed or	Noise	V		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and tl	his can be arranged fo	or an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:		-0		-161-		Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	- HE			TIS		Operation	~		
R = rust PT = paint defe				\prod		Noise	~		
C = crack						Clutch	~		
P = pin dent	HID				ᅰ╽	CV joints	~		
* = decals	- Alk			- Jul	AD w	Wheel bearings	V		
SC = stone chips						Brakes			
W = significan	t scuffs S		DP		P W	Performance	~		
Podylog	action Commonts	Note: son	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread depth of tyres)			
					Left front				
						Right front)	mm
						Left rear	4	1	mm
Conditions During Body Inspection: Wet						Right rear		3 mr	
						Spare		Yes	
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation		~	
Interior Comments						Electrical / Accessories	1		
Seats	Poor					Head lights	~		
	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	Good					Dashboard warning lights	~		
	Average					Wipers (front & rear)	~		
Dashboa	ru					Window winder FL	~		
						Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)		~	
						CD (basic test only)		~	
						Number of keys	2	2	
Road Con	ditions During Test	Drive:	Wet			Central locking	~		
Г			C I			Remote locking	~		
-	ming Mechanism:	Timing (14		Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspector	d by: Eddie Marsters					Date: 05 Sep 20)19		
Inspected by: Eddie Marsters Date: 05 Sep 2019									

I have read and understood this condition guide.

Name:

Signature: