

Report ID: 17,778,477 Version: 2 07 Sep 2019 Created:

Make:	Toyota	Model:	Hilux	Body Style:	Utility		Pass	Fail	N/A
Year:	2012	<b>Registration:</b>	GPD632	Reg Expiry:	29 Oct 2019	Engine	1		
WoF Expiry:	26 Oct 2019	Odometer:	155,769 Kms	Good No:	17778477	Oil level	~		
VIN:	MR0FZ22G001186561	Next Service:	due	Service Histor	<b>y:</b> Yes	Smoke & fumes	~		
						Performance	r		
	port is not a warranty	aration is made	for any and milaago	Parts have not	been dismonthed or	Noise	V		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.									
a full mechar	nical inspection prior to	purchase and t	his can be arranged fo	or an additional o	harge.	Coolant condition	~		
						Performance	v		
Key:		-0	P D			Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent				The	EIU/	Operation	~		
R = rust PT = paint def				$\prod$	JHIA	Noise	~		
C = crack					D	Clutch	~		
P = pin dent						CV joints	~		
* = decals	ssc PIP				ENR	Wheel bearings	~		<u> </u>
SC = stone chips						Brakes			
W = significant scuffs									T
		Notorcom	ne defects & blemishes			Hand Brake	レ レ		-
1 .	pection Comments			s may not be disp	hayed in the diagram		-		
Rear tray frame rusted out in places. Both running boards have damage						<b>Tyres</b> (lowest observed tread depth of tyres)			-
						Left front		1	mm
						Right front		1	mm
						Left rear		3	mm
Conditions During Body Inspection: Dry						Right rear	8 mm		
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
	inage & onder bor	inet inspectio	<u>on comments</u>			Suspension	1	-	1
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
Carnota	Average					Tail lights	~		
Carpets						Indicators	~		
Panels	Average					Dashboard warning lights	~		
	Average					Wipers (front & rear)	~		
Dashboa	ird					Window winder FL	~		
						Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		1
						Number of keys	2	L	L
Road Conditions During Test Drive: Dry						Central locking	V		
Road Conditions During Test Drive: Dry						Remote locking	~		<u> </u>
Engine Ti	ming Mechanism:	Cambel	t			Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: Yes Kms: 150,000						Reversing camera			~
	•			_					
Inspected by: Eddie Marsters Date: 07 Sep 2019									

I have read and understood this condition guide.

Name: .....

Signature: .....