

Report ID: 17,778,918 Version: 1 02 Oct 2019 Created:

| Make: | Skoda | Model: | Superb | Body Style: | Wagon | | Pass | Fail | N/A |
|--|------------------------|----------------|-------------|----------------|-------------|--|----------|------------|----------|
| Year: | 2016 | Registration: | KBN733 | Reg Expiry: | 20 Dec 2019 | Engine | | | |
| WoF Expiry: | | Odometer: | 130,813 Kms | Good No: | 17778918 | Oil level | ~ | | |
| VIN: | TMBMJ9NP1H701448 | | | Service Histor | | Smoke & fumes | ~ | | |
| | | | | | , 103 | Performance | ~ | | |
| | port is not a warranty | | | | | Noise | ~ | | |
| This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge. | | | | | | Cooling System | | | |
| | | | | | | Coolant condition | | | <u> </u> |
| | | _ | | | | Performance | ~ | | |
| Key: | | -0 | | | | Radiator / Hoses (visual) | ~ | | |
| S = scratch | | | | | | Transmission | | | |
| D = dent | | | | 1 - L | EID . | Operation | | | T |
| R = rust | mp | | | 10 | | Noise | v | | |
| PT = paint def C = crack | ect III | | | + | | Clutch | ~ | | |
| P = pin dent | Ho | | | - | | CV joints | | | ~ |
| * = decals | - MIC | | | | | , | ~ | | |
| SC = stone chips | | | | | | Wheel bearings | ~ | | |
| W = significant scuffs | | | | | | Brakes | | | |
| | | | | | | Performance | ~ | | |
| Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram | | | | | | Hand Brake | ~ | 6 . | Ļ |
| | | | | | | Tyres (lowest observed tread depth of tyres) | | | |
| | | | | | | Left front | 4 mm | | |
| | | | | | | Right front | | 3 | mm |
| | | | | | | Left rear | | 3 | mm |
| Conditions During Body Inspection: Wet | | | | | | Right rear | 4 mm | | |
| Under Carriage & Under Bonnet Inspection Comments | | | | | | Spare Yes | | | |
| <u>Under Ca</u> | mage & Under Bor | inet inspectic | on comments | | | Suspension | | | |
| | | | | | | Suspension performance | ~ | | |
| | | | | | | Steering performance | ~ | | |
| | | | | | | Shock absorbers | ~ | | |
| | | | | | | Air Conditioning / Heater | | | |
| | | | | | | Operation | ~ | | |
| Interior Comments Good | | | | | | Electrical / Accessories | | | |
| Seats | Good | | | | | Head lights | ~ | | |
| Carpote | Good | | | | | Tail lights | ~ | | |
| Carpets | | | | | | Indicators | ~ | | |
| Panels | Good | | | | | Dashboard warning lights | ~ | | |
| Dachhar | rd Good | | | | | Wipers (front & rear) | ~ | | |
| Dashboa | iu | | | | | Window winder FL | ~ | | |
| | - | | | | | Window winder FR | ~ | | |
| General (| <u>Comments</u> | | | | | Window winder RL | ~ | | |
| | | | | | | Window winder RR | ~ | | |
| | | | | | | Rear view mirrors | ~ | | |
| | | | | | | Radio (basic test only) | ~ | | |
| | | | | | | CD (basic test only) | ~ | | |
| | | | | | | Number of keys | 2 | | |
| Road Conditions During Test Drive: Wet | | | | | | Central locking | ~ | | |
| | | | | | | Remote locking | ~ | | |
| Engine Timing Mechanism: Cambelt | | | | | | Sat. Nav. (basic test only) | ~ | | |
| Evidence | of Cam Belt Replac | ement: N | 10 | Kms: | | Reversing camera | ~ | | |
| | | | | | | | | | |
| Inspected by: Eddie Marsters Date: 02 Oct 2019 | | | | | | | | | |
| I have read and understood this condition guide. Name: | | | | | | | | | |