

Report ID: 17,781,323 Version: 1 08 Oct 2019 Created:

Make: Toyota Model: Corolla Body Style: Hatchback	P	ass Fail	N/A
Year: 2015 Registration: JML620 Reg Expiry: 09 Dec 2019			1
WoF Expiry: 10 Oct 2020 Odometer: 45,295 Kms Good No: 17781323 Oil le		/	
	ke & fumes		
	ormance		
Note: This report is not a warranty	-		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantied or	ng System		
ill mechanical inspection prior to purchase and this can be arranged for an additional charge.		/	
	ormance		
Keve SC S S	ator / Hoses (visual)		
S = scratch	mission		
D=dent	ration		
PT = paint defect C = crack		, 	
			~
SC = stone chips	el bearings		
W = significant scuffs S P S P S P S P S P	-		1
	ormance		
Body Inspection Comments	Brake		Ļ
	Tyres (lowest observed tread depth of tyres)		
		4.2	mm
	t front	4.5	mm
		6.0	mm
Conditions During Body Inspection: Dry Right	t rear	6.0	mm
	Spare Yes		
Under Carriage & Under Bonnet Inspection Comments Suspe			
Susp	ension performance	·	
Steer	ring performance	•	
Shoc	k absorbers	•	
Air Co	nditioning / Heater		
	ration 🗸	•	
	ical / Accessories		
Seats Good Head	l lights 🗸	•	
Carpets Good Tail li	ights 🗸	/	
	ators 🗸	/	
Panels Good Dash	board warning lights	/	
	ers (front & rear)	/	
L Dachboard	low winder FL	/	
	low winder FR	/	
General Comments Wind	low winder RL	/	
Winc	low winder RR 🛛	/	
Rear	view mirrors	/	
Radie	o (basic test only)	/	
CD (ł	oasic test only)	/	
Num	ber of keys 2		•
Road Conditions During Test Drive: Dry Cent	ral locking	/	
Remo	ote locking	/	
Engine Timing Mechanism: Timing Chain	Nav. (basic test only)		~
	•		1
Suidence of Com Dolt Donle company. Next A suit suit is Kings	rsing camera	/	

I have read and understood this condition guide.

Name:

Signature: