

Report ID: 17,781,470 Version: 1 15 Nov 2019 Created:

Make:	Hyundai	Model:	145	Body Style:	Sedan		Pass	Fail	N/A
Year:	2012	Registration:	GQS65	Reg Expiry:	18 Dec 2019	Engine			1
WoF Expiry:	24 Jan 2020	Odometer:	156,187 Kms	Good No:	17781470	Oil level		~	
VIN:	KMHEB41AMDA5208(Next Service:	152,500kms	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	~		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechar	ical inspection prior to	purchase and tl	his can be arranged fo	or an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:		-0		-01-		Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent P = rurt SSC SSC SSC SSC SSC SSC SSC SSC SSC SS						Operation	~		
R = rust PT = paint defect C = crack						Noise	~		
						Clutch			~
P = pin dent						CV joints	~		
* = decals RSC 00						Wheel bearings	~		
SC = stone chips						Brakes			<u> </u>
W = significant scuffs SC S						Performance	~		
		Note: son	ne defects & blemishe	s may not be disc	laved in the diagram	Hand Brake	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Tyres (lowest observed tread	•	of tyre	 >s)
- Large stone chips on front of bonnet. - Stone chips in windscreen.						Left front			
- Right side of rear bumper is not aligning to right rear guard correctly.						Right front			mm
- Scratches along left side sill.						Left rear	5.		mm
						Right rear		-	
Conditions During Body Inspection: Wet							5.4 mm		
Under Carriage & Under Bonnet Inspection Comments						Spare Yes Suspension			
	inage a onder bor	meenspeede							1
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation	~		
Good						Electrical / Accessories			
Seats						Head lights	~		
Carpets	Good					Tail lights	~		
	Good					Indicators	~		
Panels	3000					Dashboard warning lights	~		
Dashboa	rd Good					Wipers (front & rear)	~		
						Window winder FL	~		<u> </u>
Gonoral	omments					Window winder FR	~		<u> </u>
General Comments - Rubber pad on one of key remotes is worn.						Window winder RL	~		<u> </u>
nubber pt	a on one of key temote	.5 15 WOTTI.				Window winder RR	~		
						Rear view mirrors	~		<u> </u>
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Wet						Central locking	~		<u> </u>
Engine Timing Mechanism: Timing Chain						Remote locking	~		<u> </u>
Engine Timing Mechanism: Timing Chain Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)			~
Evidence	or Cam Beit Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: Jason Young						Date: 30 Sep 2019			
I have read and understood this condition guide. Name:									