

Basic Vehicle Condition Guide

Report ID: 17,781,709


Version: 1

Created: 21 Oct 2019

Make: Model: Hyundai Santa FE **Body Style:** SUV Year: 2016 Registration: JWR167 Reg Expiry: 31 Dec 2019 WoF Expiry: **Odometer:** 31 Oct 2020 49,822 Kms **Good No:** 17781709 VIN: KMHST81XSGU612938 Next Service: 64,000kms **Service History:** Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

- Right front inner plastic guard panel is missing.
- Lower plastic panel in front bumper is not fitting correctly.
- Indicator lens in left side wing mirror is cracked & broken.

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

| Interior Comments | | | | |
|-------------------|------|--|--|--|
| Seats | Good | | | |
| Carpets | Good | | | |
| Panels | Good | | | |
| Dashboard | Good | | | |

General Comments

- Hand brake needs adjustment.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Jason Young Date: 15 Oct 2019

Name:

| | Pass | Fail | N/A | |
|--|-----------------|------|-----|--|
| Engine | | | | |
| Oil level | ~ | | | |
| Smoke & fumes | \(\times \) | | | |
| Performance | ~ | | | |
| Noise | ~ | | | |
| Cooling System | | | | |
| Coolant condition | ~ | | | |
| Performance | \(\triangle \) | | | |
| Radiator / Hoses (visual) | ~ | | | |
| Transmission | | | | |
| Operation | ~ | | | |
| Noise | ~ | | | |
| Clutch | \(\times \) | | | |
| CV joints | ~ | | | |
| Wheel bearings | ~ | | | |
| Brakes | • | • | | |
| Performance | ~ | | | |
| Hand Brake | | ~ | | |
| Tyres (lowest observed tread depth of tyres) | | | | |
| Left front | 5 | .0 | mm | |
| Right front | 5.0 | | mm | |
| Left rear | 8 | .0 | mm | |
| Right rear | 8.0 | | mm | |
| Spare | | Yes | | |
| Suspension | | | | |
| Suspension performance | ~ | | | |
| Steering performance | <i>V</i> | | | |
| Shock absorbers | ~ | | | |
| Air Conditioning / Heater | | | • | |
| Operation | ~ | | | |
| Electrical / Accessories | | | | |
| Head lights | ~ | | | |
| Tail lights | ~ | | | |
| Indicators | ~ | | | |
| Dashboard warning lights | ~ | | | |
| Wipers (front & rear) | \(\times \) | | | |
| Window winder FL | ~ | | | |
| Window winder FR | ~ | | | |
| Window winder RL | ~ | | | |
| Window winder RR | \(\times \) | | | |
| Rear view mirrors | ~ | | | |
| Radio (basic test only) | ~ | | | |
| CD (basic test only) | ~ | | | |
| Number of keys | 2 | I | | |
| Central locking | ~ | | | |
| Remote locking | ~ | | | |
| Sat. Nav. (basic test only) | | | ~ | |
| Reversing camera | ~ | | | |
| | | | | |

Signature: