

Report ID: 17,790,326 Version: 1 Created: 23 Oct 2018

Make:	Holden	Model:	Colorado	Body Style:	Utility		Pass	Fail	N/A
Year:	2009	Registration:	ETN236	Reg Expiry:	08 Oct 2018	Engine	1	1	
WoF Expiry:	15 Dec 2018	Odometer:	282,586 Kms	Good No:	17790326	Oil level	~		
VIN:	MMMTFR85H8H56994	Next Service:	279000	Service Histor	V: No	Smoke & fumes	r		
						Performance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	~		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition	~		
	CCW					Performance	r		
Key: SCW S SD S						Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust SW						Operation	~		
PT = paint defect						Noise	r		
C = crack						Clutch	V		
P = pin dent						CV joints			~
* = decals SC 919 S						Wheel bearings	V		
SC = stone chips						Brakes			
W = significant scuffs S D S D S						Performance 🖌			
Rody Inspection Commenter Note: some defects & blemishes may not be displayed in the diagram						Hand Brake	~		
Body Inspection Comments Windscreen chips						Tyres (lowest observed tread	ad depth of tyres)		es)
Tints damaged						Left front	Left front 0.0		
						Right front		.0	mm
						Left rear		.0	mm
Conditions During Body Inspection: Dry						Right rear		.0	mm
						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Front brake pads low						Suspension performance	~		
Rear shock bushes worn Rear spring bushes starting to wear						Steering performance	~		
Front tyres worn						Shock absorbers	~		
						Air Conditioning / Heater	1		
						Operation		~	
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
<u></u>	Average					Tail lights	~		
Carpets	Avelage					Indicators	~		
Panels	Average					Dashboard warning lights	~		
	A					Wipers (front & rear)	~		
Dashboa	rd Average					Window winder FL	~		
	I				J	Window winder FR	~		
General (<u>Comments</u>					Window winder RL	~		
Hand brake excessive travel						Window winder RR	~		
A/c not col	L					Rear view mirrors	V		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
L							1	1	
Inspected by: Greg Morgan Date: 23 Oct 2018									
I have read and understood this condition guide. Name:									