

Report ID: 17,790,825 Version: 1 21 Nov 2018 Created:

Make:	Toyota	Model:	Hilux	Body Style:	Utility		Pass	Fail	N/A
Year:	2011	Registration:	FYN599	Reg Expiry:	20 Mar 2019	Engine	I		I
WoF Expiry:		Odometer:	122,400 Kms	Good No:	17790825	Oil level	~		
VIN:	MR0FZ22G501050085	Next Service:	125000	Service Histor	y: Yes	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	unting is mode	for one and miles as	Danta hava nat	heen discontined or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and tl	his can be arranged fo	or an additional o	charge.	Coolant condition	~		
						Performance	~		
Key:		-0	SC S	-161-		Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust						Operation	~		
R = rust PT = paint defe				$\left(\left \right\rangle \right)$		Noise	~		
C = crack						Clutch	~		
P = pin dent	HID				거네	CV joints	~		
* = decals	sc 616			-No-		Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs						Performance	~		
Body Incr		Note: son	ne defects & blemishes	may not be disp	blayed in the diagram	Hand Brake	~		
Body Inspection Comments Left hand cant rail trim missing						Tyres (lowest observed tread depth of tyres)			
					Left front	3	.5	mm	
						Right front	4		mm
						Left rear	5		mm
Conditions During Body Inspection: Dry						Right rear	5	-	mm
Conditions During Body Inspection: Dry						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments					Suspension				
Minor surfa	ce rust radiator lower su	upport panel				Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
<u></u>	Average					Tail lights	~		
Carpets	Average					Indicators	~		
Panels	Average					Dashboard warning lights	~		
	Average					Wipers (front & rear)	~		
Dashboa	rd					Window winder FL	~		
	·					Window winder FR	~		
General Comments						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
,						Remote locking	~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lo	Kms:		Reversing camera			~
									-
Inspected by: Greg Morgan Date: 16 Nov 2018									

I have read and understood this condition guide.

Name:

Signature: