

Basic Vehicle Condition Guide

Report ID: 17,791,581


Version: 1

Created: 14 Dec 2018

Make: Model: Hyundai Santa FE **Body Style:** SUV Year: 2014 Registration: HSC204 Reg Expiry: 15 Jan 2019 WoF Expiry: **Odometer: Good No:** 18 Oct 2019 117,666 Kms 17791581 VIN: KMHST81XSEU343495 Next Service: 125000 **Service History:** Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Windscreen chips

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

<u>Interior Comments</u>			
Seats	Average		
Carpets	Average		
Panels	rear trim piece missing		
Dashboard	Average		

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Greg Morgan

Create	d: 1	4 Dec 2	2018
	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	<i>y y</i>		
Performance	~		
Noise	~		
Cooling System			-
Coolant condition	~		
Performance	~		
Radiator / Hoses (visual)	~		
Transmission	ļ.	!	-
Operation	~		
Noise	~		
Clutch			~
CV joints	~		
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	depth	of tyre	 es)
Left front		.0	mm
Right front	5.0		mm
Left rear	3.0		mm
Right rear	3.0		mm
Spare	,	Yes	
Suspension		103	
Suspension performance	V		
Steering performance	V		
Shock absorbers	~		
Air Conditioning / Heater	•		
Operation	~		
Electrical / Accessories			
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	~		
Wipers (front & rear)	~		
Window winder FL			
Window winder FR	V		
Window winder RL	~		
	<i>v</i>		
Window winder RR			
Rear view mirrors	•		
Radio (basic test only)	-		
CD (basic test only)	~		
Number of keys	2		1
Central locking	'		
Remote locking	~		
Sat. Nav. (basic test only)			~
Reversing camera			

13 Dec 2018

I have read and understood this condition guide. Name: Signature: