

Basic Vehicle Condition Guide

Report ID: 17,792,564


Version: 1

Created: 07 Feb 2019

Make: Model: Suzuki Jimny **Body Style:** SUV Year: 2011 Registration: **GBQ359** Reg Expiry: 26 Sep 2019 WoF Expiry: **Odometer:** 27 Sep 2019 76,844 Kms **Good No:** 17792564 VIN: JSAFJB43V00515139 Next Service: 75000 Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Rear door stay missing
Rear seats and belts removed / missing

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

| Interior Comments | | | |
|-------------------|-------------------|--|--|
| Seats | drivers seat worn | | |
| Carpets | Average | | |
| Panels | Average | | |
| Dashboard | Average | | |

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Greg Morgan

| | Pass | Fail | N/A |
|------------------------------|-----------------|---------|----------|
| Engine | | • | |
| Oil level | ~ | | |
| Smoke & fumes | ~ | | |
| Performance | \(\triangle \) | | |
| Noise | ~ | | |
| Cooling System | • | • | |
| Coolant condition | ~ | | |
| Performance | ~ | | |
| Radiator / Hoses (visual) | ~ | | |
| Transmission | • | | |
| Operation | ~ | | |
| Noise | ~ | | |
| Clutch | ~ | | |
| CV joints | | | ~ |
| Wheel bearings | ~ | | |
| Brakes | | | |
| Performance | ~ | | |
| Hand Brake | ~ | | |
| Tyres (lowest observed tread | d depth | of tyre | es) |
| Left front | 6 | .0 | mm |
| Right front | 6.0 | | mm |
| Left rear | 6.0 | | mm |
| Right rear | 6.0 | | mm |
| Spare | Yes | | |
| Suspension | | | |
| Suspension performance | ~ | | |
| Steering performance | ~ | | |
| Shock absorbers | ~ | | |
| Air Conditioning / Heater | | | |
| Operation | | | ~ |
| Electrical / Accessories | | | |
| Head lights | V | | |
| Tail lights | ~ | | |
| Indicators | ~ | | |
| Dashboard warning lights | ~ | | |
| Wipers (front & rear) | ~ | | |
| Window winder FL | ~ | | |
| Window winder FR | ~ | | |
| Window winder RL | | | ./ |
| Window winder RR | | | ./ |
| Rear view mirrors | | | - |
| Radio (basic test only) | • | | |
| CD (basic test only) | <i>v</i> | | |
| Number of keys | - | | |
| | 1 | | |
| Central locking | | | ., |
| Remote locking | | | - |
| Sat. Nav. (basic test only) | | | ' |
| Reversing camera | <u></u> | | 1 |

I have read and understood this condition guide.

Name:

Signature:

01 Feb 2019

Date: