

Report ID: 17,792,593 Version: 1 07 Feb 2019 Created:

Make:	Mazda	Model:	Bt-50	Body Style:	Utility		Pass	Fail	N/A
Year:	2007	Registration:	EGF614	Reg Expiry:	16 Dec 2019	Engine		1	•
WoF Expiry:	03 Dec 2019	Odometer:	237,114 Kms	Good No:	17792593	Oil level	~		
VIN:	MM0UNY0E30066668	Next Service:	243000	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for age and mileage	Parts have not	been dismontled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and t	his can be arranged fo	or an additional o	charge.	Coolant condition	~		
						Performance	~		
Key:		-0	D D	-161-	S D	Radiator / Hoses (visual)	· ·		
S = scratch						Transmission			
D = dent	sscw 6/6				E SD	Operation	~		
R = rust PT = paint def				\prod	JHIH	Noise	~		
C = crack					SC	Clutch	~		
P = pin dent						CV joints			~
* = decals	s sc PIP			AL.	ELF SD	Wheel bearings	~		•
SC = stone chips						Brakes	V		
W = significant scuffs						Performance	~		
		Note: con		may not be disr		Hand Brake			
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram							d donth	ofture	
Windscreen chips						Tyres (lowest observed tread depth of tyres)			
						Left front	9		mm
						Right front	9		mm
						Left rear	5.		mm
Conditions During Body Inspection: Dry						Right rear 5.0 mm			
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
	inage & onder bor	metmspectic	<u>In comments</u>			Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Commonte						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
Carpote	worn					Tail lights	~		
Carpets						Indicators	~		
Panels	Average					Dashboard warning lights	~		
	Average					Wipers (front & rear)	~		
Dashboa	ra					Window winder FL	~		
						Window winder FR	~		
General Comments						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		•
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: Yes Kms: 208,500						Reversing camera			~
L			1	1					
Inspected by: Greg Morgan Date: 01 Feb 2019									

I have read and understood this condition guide.

Name:

Signature: