

Report ID: 17,795,312 Version: 1 Created: 28 Jun 2019

Make:	Holden	Model:	Cruze	Body Style:	Sedan		Pass	Fail	N/A
Year:	2010	<b>Registration:</b>	FJL343	<b>Reg Expiry:</b>	28 Jul 2019	Engine			
WoF Expiry:	19 Jun 2019	Odometer:	134,316 Kms	Good No:	17795312	Oil level	~		
VIN:	KL3JF695JAK664301	Next Service:	133000	Service Histor	<b>y:</b> Yes	Smoke & fumes	~		
						Performance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	~		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	lical inspection prior to	purchase and t	his can be arranged fo	or an additional o	harge.	Coolant condition	~		
			SC			Performance	~		
Key:		$-\infty$		500-		Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			1
R = rust						Operation	~		
PT = paint def	ect NP					Noise	~		
C = crack						Clutch	r		
P = pin dent	HIG				7414	CV joints	~		
* = decals SC 00						Wheel bearings	~		
SC = stone chips						Brakes			L
W = significant scuffs S PT W D SC PT						Performance	~		
Dadulu	action Comments	Note: son	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread	d depth	of tvre	L
Right front hub cap missing						Left front			mm
Windscreer						Right front	3		mm
						Left rear	4		mm
Conditions During Rody Inspection: Wat						Right rear			mm
Conditions During Body Inspection: Wet						Spare	3.0 mm Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
	-	·				Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	v		
						Operation	~		
Interior Comments						Electrical / Accessories	V		<u> </u>
Seats	Average	Average					~		
Seals						Head lights Tail lights			
Carpets	Average						~		
	left front c	or handle worn				~			
Panels			-			Dashboard warning lights	~		
Dashboa	rd Average					Wipers (front & rear)	~		
						Window winder FL	~		
General (	omments					Window winder FR	~		
General Comments Minor power steering noise						Window winder RL	~		<u> </u>
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Wet						Central locking	~		<u> </u>
Engine Timing Mechanism: Cambelt						Remote locking	~		<u> </u>
						Sat. Nav. (basic test only)			~
Evidence	or Cam Beit Replac	ement: N	10	Kms:		Reversing camera			~
Inspected by: Greg Morgan						Date: 14 Jun 2019			
I have read and understood this condition guide. Name:									