

Report ID: 17,796,039

Version:

Engine Oil level Smoke & fumes

Noise

Performance

Cooling System

Transmission

Operation

Coolant condition Performance

Radiator / Hoses (visual)

15 Jan 2019 Created:

Pass

~

~


N/A

Fail

Make:	Mazda	Model:	Bt-50	Body Style:	Utility
Year:	2009	Registration:	EYP498	Reg Expiry:	10 Jul 2019
WoF Expiry:	13 Dec 2019	Odometer:	119,002 Kms	Good No:	17796039
VIN:	MM0UNY0E40083091	Next Service:	118,000kms	Service Histor	y: No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

- GPS dome fitted to roof.
- Stone chips in windscreen.
- Left rear tail light has broken lens.
- Water inside both rear tail lights.

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

- Coolant system/radiator needs a flush.
- Right rear shock is leaking.

Interior Comments	nterior Comments			
Seats	Good			
Carpets	Good			
Panels	Good			
Dashboard	Good			

General Comments

- Clutch starting to slip under heavy loads.
- One of key remotes is not working to lock & unlock vehicle.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: Kms:

Noise 1 Clutch J CV joints 1 Wheel bearings Brakes Performance **Hand Brake** Tyres (lowest observed tread depth of tyres) Left front mm 5.0 Right front 5.2 mm Left rear 4.8 mm Right rear mm 5.1 Spare Yes Suspension Suspension performance 1 Steering performance Shock absorbers ~ Air Conditioning / Heater Operation **Electrical / Accessories Head lights** 1 Tail lights Indicators / Dashboard warning lights / Wipers (front & rear) / Window winder FL Window winder FR 1 Window winder RL Window winder RR Rear view mirrors / Radio (basic test only) ~ CD (basic test only) 1 Number of keys 2 Central locking Remote locking ~ Sat. Nav. (basic test only) Reversing camera

inspected by: Jason roung

15 Jan 2019

Date: