

Report ID: 17,796,056 Version: 2 17 Jan 2019 Created:

Make:	Hyundai	Model:	Santa FE	Body Style:	SUV		Pass	Fail	N/A	
Year:	2015	Registration:	JCW618	Reg Expiry:	26 Feb 2019	Engine				
WoF Expiry:	27 May 2019	Odometer:	218,165 Kms	Good No:	17796056	Oil level	~			
VIN:	KMHST81XSFU474702	Next Service:	228,229kms	Service Histor	y: Yes	Smoke & fumes	~			
						Performance	~			
	port is not a warranty	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System				
a full mechan	ical inspection prior to	purchase and t	his can be arranged fo	r an additional o	harge.	Coolant condition	~			
	S SC		C C DT		S PT	Performance	~			
Key:	Lase (-0	S SPT		SPI	Radiator / Hoses (visual)	~			
S = scratch						Transmission				
D = dent R = rust	s sc			715	SW	Operation	~			
PT = paint defe	ect NP	FI		$\left[\left(\right) \right]$		Noise	~			
C = crack					R SC	Clutch			~	
P = pin dent	I SACONTHE				74114	CV joints	~			
* = decals	SDSCW 91			The second	ED s	Wheel bearings	~			
SC = stone chips						Brakes				
W = significant scuffs S SC S PT PT P S S D R PT						Performance	~			
Body Incr	portion Commonts	Note: son	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~			
Body Inspection Comments - Stone chips in front windscreen.						Tyres (lowest observed tread depth of tyres)			es)	
- Bottom edge of right rear tail light is cracked & broken.						Left front	Left front 9 mr			
- Paintwork faded from where stickers have been on both left side doors, left rear guard, right rear guard & right rear door.						Right front	9	9.5 mm		
- Top of bonnet has two large dents in middle of it.						Left rear	9 mm		mm	
Conditions During Body Inspection: Dry						Right rear	9.2 mm		mm	
						Spare	Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension				
						Suspension performance	~			
						Steering performance	~			
Shock absor						Shock absorbers	~			
		Air Conditioning / Heater								
						Operation	~			
Interior Comments						Electrical / Accessories	1			
Seats	Good					Head lights	~			
	Good					Tail lights		~		
Carpets						Indicators	~			
Panels	Average					Dashboard warning lights	~			
	Average					Wipers (front & rear)	~			
Dashboa	rd					Window winder FL	~			
						Window winder FR	~			
General Comments					Window winder RL	~				
- Rubber gr	ip missing off handbrak	e pedal.				Window winder RR	~			
						Rear view mirrors	~			
						Radio (basic test only)	~			
						CD (basic test only)	~			
						Number of keys	2			
Road Conditions During Test Drive: Dry Central locking							~			
			•			Remote locking	~			
-	ming Mechanism:	Timing				Sat. Nav. (basic test only)			~	
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~			
Increat-	Inspected by: Jason Young Date: 17 Jan 2019									
Inspected by, Jason roung Date: 17 Jan 2019										

I have read and understood this condition guide.

Name:

Signature: