
Basic Vehicle Condition Guide

Report ID: 17,797,364
Version: 1
Created: 06 Jun 2019

Make:	Ford	**Model:**	Kuga	**Body Style:**	SUV
Year:	2014	**Registration:**	HUH988	**Reg Expiry:**	04 Dec 2019
WoF Expiry:	14 Dec 2019	**Odometer:**	61,989 Kms	**Good No:**	17797364
VIN:	WF0AXXWPMAEM374	**Next Service:**	79,000 kms	**Service History:**	Yes

Note: This report is not a warranty
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key:
S = scratch
D = dent
R = rust
PT = paint defect
C = crack
P = pin dent
* = decals
SC = stone chips
W = significant scuffs



Note: some defects & blemishes may not be displayed in the diagram

Body Inspection Comments

- Crack in windscreen on drivers side.
- Trim missing from front bumper.
- Boot is out of alignment, not opening fully.
- Left rear spotlight is cracked.
- Right front door is out of alignment.

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

- Heavily pulling to the left while driving, wheel alignment is overdue.
- Gear change isn't changing smoothly at all times.

Interior Comments

Seats	Good
Carpets	Good
Panels	Good
Dashboard	Good

General Comments

- All four doors have small metal trim stuck on there edges.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain
Evidence of Cam Belt Replacement: Not Applicable Kms:

	Pass	Fail	N/A
Engine			
Oil level	✔		
Smoke & fumes	✔		
Performance	✔		
Noise	✔		
Cooling System			
Coolant condition	✔		
Performance	✔		
Radiator / Hoses (visual)	✔		
Transmission			
Operation	✔		
Noise	✔		
Clutch			✔
CV joints	✔		
Wheel bearings	✔		
Brakes			
Performance	✔		
Hand Brake	✔		
Tyres (lowest observed tread depth of tyres)			
Left front	4.3 mm		
Right front	5.2 mm		
Left rear	4.3 mm		
Right rear	4.7 mm		
Spare	Yes		
Suspension			
Suspension performance	✔		
Steering performance	✔		
Shock absorbers	✔		
Air Conditioning / Heater			
Operation	✔		
Electrical / Accessories			
Head lights	✔		
Tail lights	✔		
Indicators	✔		
Dashboard warning lights	✔		
Wipers (front & rear)	✔		
Window winder FL	✔		
Window winder FR	✔		
Window winder RL	✔		
Window winder RR	✔		
Rear view mirrors	✔		
Radio (basic test only)	✔		
CD (basic test only)	✔		
Number of keys	2		
Central locking			✔
Remote locking	✔		
Sat. Nav. (basic test only)			✔
Reversing camera	✔		

Inspected by: Anna-Lise Ferguson Date: 03 Jun 2019

I have read and understood this condition guide. Name: ..... Signature: .....