


<b>Make:</b>	Daihatsu	<b>Model:</b>	Charade	<b>Body Style:</b>	Hatchback
<b>Year:</b>	2004	<b>Registration:</b>	CRP515	<b>Reg Expiry:</b>	26 Jul 2019
<b>WoF Expiry:</b>	03 May 2019	<b>Odometer:</b>	154,441 Kms	<b>Good No:</b>	17797607
<b>VIN:</b>	JDAL251S001035705	<b>Next Service:</b>	163,071kms	<b>Service History:</b>	No

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

## Key:

S = scratch  
D = dent  
R = rust  
PT = paint defect  
C = crack  
P = pin dent  
\* = decals  
SC = stone chips  
W = significant scuffs



## Body Inspection Comments

Note: some defects & blemishes may not be displayed in the diagram

- Rubber gutter trim on left side of roof is missing.
- Paint faded on rear bumper, right rear guard & right rear door.
- Dent in left side sill.
- Left rear tyre below legal tread depth limit, needs replaced.

Conditions During Body Inspection: Dry

## Under Carriage & Under Bonnet Inspection Comments

- Minor oil leak from gearbox.

## Interior Comments

Seats	Average
Carpets	Average
Panels	Good
Dashboard	Good

## General Comments

- Stitching split in two places on base of drivers seat.
- Plastic handle on side off drivers seat has come off, is sitting inside vehicle.
- Radio keeps turning off as need security code for it.
- Right front radio speaker is not working.
- Front carpets are worn.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: Yes Kms: 97,800

	Pass	Fail	N/A
<b>Engine</b>			
Oil level	✓		
Smoke & fumes	✓		
Performance	✓		
Noise	✓		
<b>Cooling System</b>			
Coolant condition	✓		
Performance	✓		
Radiator / Hoses (visual)	✓		
<b>Transmission</b>			
Operation	✓		
Noise	✓		
Clutch	✓		
CV joints	✓		
Wheel bearings	✓		
<b>Brakes</b>			
Performance	✓		
Hand Brake	✓		
<b>Tyres</b> (lowest observed tread depth of tyres)			
Left front	4.0	mm	
Right front	3.8	mm	
Left rear	1.4	mm	
Right rear	2.8	mm	
Spare	Yes		
<b>Suspension</b>			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
<b>Air Conditioning / Heater</b>			
Operation	✓		
<b>Electrical / Accessories</b>			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL	✓		
Window winder RR	✓		
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)	✓		
Number of keys	2		
Central locking	✓		
Remote locking			✓
Sat. Nav. (basic test only)			✓
Reversing camera			✓

Inspected by: Jason Young

Date: 04 Mar 2019

I have read and understood this condition guide.

Name: .....

Signature: .....