

Report ID: 17,797,624 Version: 5 12 Jul 2019 Created:

Make:	Ford	Model:	Ranger	Body Style:	Utility		Pass	Fail	N/A
Year:	2014	Registration:	HHN483	Reg Expiry:	26 May 2019	Engine			
WoF Expiry:	13 Jun 2020	Odometer:	71,832 Kms	Good No:	17797624	Oil level	~		
VIN:	MNAWMBE80DW2245	Next Service:	74,000kms	Service Histor	<b>y:</b> Yes	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for ago and milaago	Darts have not	been dismonthed or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and tl	nis can be arranged fo	r an additional o	harge.	Coolant condition	~		
		_				Performance	~		
Key:		-0	SD	-161-	DP	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent SSC OF SP						Operation	~		
R = rust PT = paint defe				r In	JHIA	Noise	~		
C = crack				+		Clutch	~		
P = pin dent						CV joints	•		~
* = decals	PSC PSC			AL.	ENPR-	Wheel bearings	~		•
SC = stone chips						Brakes			
W = significant scuffs S D D P						Performance			
		Noto: con	ne defects & blemishes			Hand Brake	-		
	pection Comments	Note. son	le délects & biennisnes	illiay not be disp	hayed in the diagram			- <b>f t</b> wa	
Windscreen stone chips Dachboard light flaching (speedo, not warning lights)						Tyres (lowest observed tread depth of tyres)			
Dashboard light flashing (speedo, not warning lights)						Left front		3	mm
						Right front	5		mm
						Left rear		3	mm
Conditions During Body Inspection: Dry						Right rear	3 mm		
Under Corriges & Under Depart Increation Comments						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Rear wheel	drive					Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
Carpote	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	Good					Dashboard warning lights	~		
	Good					Wipers (front & rear)	~		
Dashboa	ra					Window winder FL	~		
						Window winder FR	~		
General Comments						Window winder RL			~
						Window winder RR			~
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		·
Road Conditions During Test Drive: Dry						Central locking	~		
			•			Remote locking	~		
Engine Tir	ming Mechanism:	Timing	Chain			Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera			~
Inspected by: Ca Thach Date: 12 Jul 2019									

I have read and understood this condition guide.

Name: .....

Signature: .....