

# **Basic Vehicle Condition Guide**

Report ID: 17,797,790


Version: 1

12 Mar 2019 Created:

Make: Model: Mazda Bt-50 **Body Style:** Utility Year: 2015 Registration: HZR744 Reg Expiry: 25 May 2019 WoF Expiry: **Odometer:** 02 Mar 2019 161,987 Kms **Good No:** 17797790 VIN: MM0UP0YF10023930! Next Service: 170,000kms Service History:

#### Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



## **Body Inspection Comments**

- Screw holes on inside lip on left front guard, where an aerial has been attached.
- Stone chips in windscreen.
- Both left & right side tail light have scratches on tail light lenses.
- Small hole in right side of rear bumper.

Conditions During Body Inspection: Dry

#### **Under Carriage & Under Bonnet Inspection Comments**

- Front brake pads wearing low.
- Plastic engine cover missing off top of engine.

Interior Comments			
Seats	Good		
Carpets	Good		
Panels	Average		
Dashboard	Good		

### **General Comments**

- Revision mirror bracket is loose & needs attention.
- Plastic trim on side of drivers seat has a broken clip.

Road Conditions During Test Drive: Dry

**Engine Timing Mechanism: Timing Chain** 

**Evidence of Cam Belt Replacement:** Not Applicable Kms:

12 Mar 2019 Inspected by: Jason Young Date:

Name: .....

	Pass	Fail	N/A		
Engine					
Oil level	~				
Smoke & fumes	V V				
Performance	~				
Noise	~				
Cooling System					
Coolant condition	\( \times \)				
Performance	~				
Radiator / Hoses (visual)	~				
Transmission					
Operation	<b>V</b>				
Noise	~				
Clutch			~		
CV joints	~				
Wheel bearings	~				
Brakes					
Performance	~				
Hand Brake	~				
Tyres (lowest observed tread depth of tyres)					
Left front	5	.0	mm		
Right front	5	.0	mm		
Left rear	6.0		mm		
Right rear	6.0		mm		
Spare		Yes			
Suspension		ı			
Suspension performance	~				
Steering performance	~				
Shock absorbers	~				
Air Conditioning / Heater					
Operation	~				
Electrical / Accessories			I		
Head lights	•				
Tail lights	•				
Indicators	•				
Dashboard warning lights	•				
Wipers (front & rear)  Window winder FL	•				
	<i>V</i>				
Window winder FR Window winder RL	-				
Window winder RR	V V V V V V				
Rear view mirrors	./				
Radio (basic test only)					
CD (basic test only)					
Number of keys	1				
Central locking	1				
Remote locking	1				
Sat. Nav. (basic test only)			1		
Reversing camera	1				
neversing carriera	_				

Signature: .....