

Report ID: 17,798,296 Version: 1 17 Apr 2019 Created:

Make:	Holden	Model:	Colorado	Body Style:	Utility		Pass	Fail	N/A	
Year:	2012	<b>Registration:</b>	GNR455	<b>Reg Expiry:</b>	29 Oct 2019	Engine		L		
WoF Expiry:	15 Dec 2019	Odometer:	181,389 Kms	Good No:	17798296	Oil level	~			
VIN:	MMU145DH0DH6256	Next Service:	196,000kms	Service Histor	<b>y:</b> Yes	Smoke & fumes	~			
						Performance	~			
	port is not a warranty	aration is made	for age and mileage	a Parts have not	been dismantled or	Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System				
a full mechar	ical inspection prior to	purchase and tl	nis can be arranged f	or an additional o	harge.	Coolant condition	~		1	
						Performance	~			
Key:	SC	-0	SP S	-01-		Radiator / Hoses (visual)	~			
S = scratch						Transmission	Transmission			
D = dent	s sc					Operation	~			
R = rust PT = paint def					JHIH	Noise	~			
C = crack				+	SC	Clutch	~			
P = pin dent						CV joints	~			
* = decals	PSC PSC			The	ENPR-	Wheel bearings	~			
SC = stone chips						Brakes	v			
W = significant scuffs SC SP						Performance	~		1	
		Note: con			laved in the diagram	Hand Brake	~			
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram							•	~ <b>f t</b>	<u> </u>	
- GPS dome fitted to roof. - Plastic centre caps missing off left & right rear wheels.						<b>Tyres</b> (lowest observed tread depth of tyres)				
- Plastic Cel	itte caps missing on leit	. a right rear whe	ers.			Left front	3.		mm	
						Right front	2		mm	
						Left rear	2.		mm	
Conditions During Body Inspection: Dry						Right rear				
Under Carriage & Under Bonnet Inspection Comments						Spare Yes				
	-		on Comments			Suspension				
- Minor leal	from right front drive s	seal.				Suspension performance	~			
						Steering performance	~			
						Shock absorbers	~			
						Air Conditioning / Heater				
						Operation	~			
Interior Comments						Electrical / Accessories				
Seats	Good					Head lights	~			
Coursets	Good					Tail lights	~			
Carpets						Indicators	~			
Panels	Good					Dashboard warning lights	~			
	. Good					Wipers (front & rear)	~			
Dashboa	rd					Window winder FL	~		1	
	· ·					Window winder FR	~		1	
General Comments						Window winder RL			~	
						Window winder RR			~	
						Rear view mirrors	~		1	
						Radio (basic test only)	V		<u> </u>	
						CD (basic test only)	~		1	
						Number of keys	1	l		
Road Conditions During Test Drive: Dry						Central locking	~			
Road Conditions During Test Drive: Dry						Remote locking	~			
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)	-		~	
Evidence of Cam Belt Replacement: Yes Kms: 150,928						Reversing camera			~	
	•	-								
Inspecte	d by: Jason Young					Date: 02 Apr 20	19			

I have read and understood this condition guide.

Name: .....

Signature: .....