

Report ID: 17,798,470


Version: 1

Created: 15 Apr 2019

| Make: | Mazda | Model: | Mazda3 | Body Style: | Hatchback |
|-------------|-------------------|---------------|------------|----------------|-----------------|
| Year: | 2015 | Registration: | JBM509 | Reg Expiry: | 20 Oct 2019 |
| WoF Expiry: | 21 Apr 2019 | Odometer: | 88,583 Kms | Good No: | 17798470 |
| VIN: | JM0BM547810168505 | Next Service: | 88,000kms | Service Histor | r y: Yes |

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Note: some defects & blemishes may not be displayed in the diagram

- Left side of front bumper has broken clips & is not fitting to left front guard correctly.
- Badges have been taken off rear tailgate & are sitting in glovebox.

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

| Interior Comments | | | | | |
|-------------------|------|--|--|--|--|
| Seats | Good | | | | |
| Carpets | Good | | | | |
| Panels | Good | | | | |
| Dashboard | Good | | | | |

General Comments

Inspected by:

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Date: 15 Apr 2019

| | Pass | Fail | N/A | | | | |
|------------------------------|-----------------|---------|-----|--|--|--|--|
| Engine | | | | | | | |
| Oil level | ~ | | | | | | |
| Smoke & fumes | \(\times \) | | | | | | |
| Performance | ~ | | | | | | |
| Noise | ~ | | | | | | |
| Cooling System | | | | | | | |
| Coolant condition | \(\times \) | | | | | | |
| Performance | ~ | | | | | | |
| Radiator / Hoses (visual) | ~ | | | | | | |
| Transmission | | | | | | | |
| Operation | ~ | | | | | | |
| Noise | ~ | | | | | | |
| Clutch | | | ~ | | | | |
| CV joints | > | | | | | | |
| Wheel bearings | ~ | | | | | | |
| Brakes | | | | | | | |
| Performance | ~ | | | | | | |
| Hand Brake | ~ | | | | | | |
| Tyres (lowest observed tread | depth | of tyre | es) | | | | |
| Left front | 5 | .5 | mm | | | | |
| Right front | 5 | .5 | mm | | | | |
| Left rear | 5 | .5 | mm | | | | |
| Right rear | 5 | .5 | mm | | | | |
| Spare | | Yes | | | | | |
| Suspension | | | | | | | |
| Suspension performance | > | | | | | | |
| Steering performance | V | | | | | | |
| Shock absorbers | > | | | | | | |
| Air Conditioning / Heater | | | | | | | |
| Operation | > | | | | | | |
| Electrical / Accessories | | | | | | | |
| Head lights | ~ | | | | | | |
| Tail lights | ~ | | | | | | |
| Indicators | ~ | | | | | | |
| Dashboard warning lights | ~ | | | | | | |
| Wipers (front & rear) | \(\times \) | | | | | | |
| Window winder FL | ~ | | | | | | |
| Window winder FR | \(\triangle \) | | | | | | |
| Window winder RL | ~ | | | | | | |
| Window winder RR | V | | | | | | |
| Rear view mirrors | ~ | | | | | | |
| Radio (basic test only) | ~ | | | | | | |
| CD (basic test only) | | | ~ | | | | |
| Number of keys | 2 | | | | | | |
| Central locking | ~ | | | | | | |
| Remote locking | ~ | | | | | | |
| Sat. Nav. (basic test only) | ~ | | | | | | |
| Reversing camera | ~ | | | | | | |
| | | | | | | | |

I have read and understood this condition guide.

Jason Young

Name:

Signature: