


Make:	Ford	Model:	Ranger	Body Style:	Utility
Year:	2013	Registration:	GYN40	Reg Expiry:	24 Sep 2019
WoF Expiry:	25 Jun 2019	Odometer:	96,068 Kms	Good No:	17799740
VIN:	MNAUM2F50DW1729	Next Service:	97,000kms	Service History:	Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key:

S = scratch
D = dent
R = rust
PT = paint defect
C = crack
P = pin dent
* = decals
SC = stone chips
W = significant scuffs



Body Inspection Comments

Note: some defects & blemishes may not be displayed in the diagram

- Mark in paintwork on bonnet, from where a decal has been.
- 3 x small stone cracks in left side of windscreen.
- Stone chips in windscreen.
- GPS dome & orange light fitted to roof, the orange light is not fitting correctly down flat to roof surface.
- Right rear tyre needs replaced. outside edge worn.

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

- Plastic engine cover is missing off top of engine.

Interior Comments

Seats	Good
Carpets	Good
Panels	Good
Dashboard	Good

General Comments

- Plastic trim on side of drivers seat has a broken clip.
- Screw holes in left side of centre console, screw holes in dashboard & about 15mm hole in lower left side of dashboard.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain
Evidence of Cam Belt Replacement: Not Applicable Kms:

	Pass	Fail	N/A
Engine			
Oil level	✓		
Smoke & fumes	✓		
Performance	✓		
Noise	✓		
Cooling System			
Coolant condition	✓		
Performance	✓		
Radiator / Hoses (visual)	✓		
Transmission			
Operation	✓		
Noise	✓		
Clutch	✓		
CV joints	✓		
Wheel bearings	✓		
Brakes			
Performance	✓		
Hand Brake	✓		
Tyres (lowest observed tread depth of tyres)			
Left front	4.0	mm	
Right front	4.4	mm	
Left rear	5.2	mm	
Right rear	0.0	mm	
Spare	Yes		
Suspension			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
Air Conditioning / Heater			
Operation	✓		
Electrical / Accessories			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL			✓
Window winder RR			✓
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)	✓		
Number of keys	1		
Central locking	✓		
Remote locking	✓		
Sat. Nav. (basic test only)			✓
Reversing camera			✓

Inspected by: Jason Young

Date: 07 Jun 2019

I have read and understood this condition guide.

Name:

Signature: