

Basic Vehicle Condition Guide

Report ID: 17,805,527

Pass

1

~

1

1

1

1

Tyres (lowest observed tread depth of tyres)

Version:

Engine

Oil level Smoke & fumes

Noise

Performance

Cooling System Coolant condition Performance

Transmission Operation

Noise

Clutch

Brakes

CV joints Wheel bearings

Performance Hand Brake

Left front

Left rear

Right rear

Suspension

Operation

Head lights Tail lights Indicators

Suspension performance Steering performance

Shock absorbers Air Conditioning / Heater

Electrical / Accessories

Dashboard warning lights

Wipers (front & rear)

Window winder FL Window winder FR

Window winder RL Window winder RR Rear view mirrors

Radio (basic test only)

CD (basic test only)

Number of keys

Central locking

Spare

Right front

Radiator / Hoses (visual)

Created: 26 Apr 2019

Fail

N/A

mm

mm

mm

 mm

4

3

V

/

/

1


1

1

3

Yes

Make: Model: **Body Style:** Toyota Hilux Utility Year: 2014 Registration: HJS61 Reg Expiry: 07 Jul 2019 WoF Expiry: 01 Apr 2020 **Odometer: Good No:** 121,723 Kms 17805527



Interior Comments					
Seats	driver seat worn				
Carpets	driver mat hole				
Panels	Average				
Dashboard	screw holes dashboard				

General Comments

Inspected by:

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt **Evidence of Cam Belt Replacement:**

John Lindsay

I have read and understood this condition guide.

No

	Remote locking	/							
	Sat. Nav. (basic test only)		~						
Kms:	Reversing camera		~						
Date: 26 Apr 2019 Name: Signature:									

V	IIV:	MKUFZ22G	901201302	Next Service:	120500		Service Histor	y: NO	
T d	iagnostic te	a guide or sting under	nly. Conside taken. The v	ration is made ehicle has beer purchase and tl	driven up	to 50km/h	from cold. The	Vendor recor	
S: D R PT C P *:	Chip winds Light on ca Lights on fr	ps t scuffs S P	omments	Note: son	D*	S D S D S D A blemishes	may not be disp	SP	S D W
	Conditio	ns During	Body Insp	ection:	Dry				
	<u>Under Ca</u>	rriage & L	Jnder Bon	net Inspectio	on Comm	<u>ents</u>			
	Interior C	omments	-						
	Seats		driver seat	worn					
	Carpets	·	driver mat l	hole					