

Report ID: 17,805,570 Version: 2 09 May 2019 Created:

Make:	Holden	Model:	Captiva 7	Body Style:	SUV		Pass	Fail	N/A
Year:	2016	Registration:	JSS696	Reg Expiry:	18 Jul 2019	Engine			
WoF Expiry:	18 Apr 2020	Odometer:	97,805 Kms	Good No:	17805570	Oil level	~		
VIN:	KL3CD2669GB510979	Next Service:	111000	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty a quide only. Conside	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	lical inspection prior to	purchase and ti	his can be arranged to	or an additional o	narge.	Coolant condition	~		
	S W		SD SD		S D	Performance	~		
Key:		=		5(0)-		Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
R = rust SC W A A A A A A A A A A A A A A A A A A						Operation 🖌			
PT = paint defe	ect NP				11111	Noise	~		
C = crack					D R SC	Clutch			~
P = pin dent	s sc dl				74116	CV joints	~		
						Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
W = significant scutts S W S D S D S D S D						Performance	~		
Body Insr	pection Comments	Note: son	ne defects & blemishes	s may not be disp	layed in the diagram	Hand Brake	~		
Rear bumper/rear guarter panel alignment						Tyres (lowest observed tread depth of tyres)			
Chip windscreen						Left front	3.0 mm		mm
						Right front	3.	.0	mm
						Left rear	8	3	mm
Conditions During Body Inspection: Dry						Right rear	8 mm		mm
						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
One key do	esn't click into remote					Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	Air Conditioning / Heater		
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	front seats	worn				Head lights	~		
Carpets	Average					Tail lights	~		
						Indicators	~		
Panels	Average					Dashboard warning lights	~		
Dashboa	Average					Wipers (front & rear)	~		
						Window winder FL	~		
						Window winder FR	~		
General	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
Engine Timing Mechanism: Timing Chain						Remote locking	~		
						Sat. Nav. (basic test only)			~
Evidence	oi Cam Beit Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected by: John Lindsay Date: 30 Apr 2019									

I have read and understood this condition guide.

Name:

Signature: