

Report ID: 17,806,039 Version: 1 06 May 2019 Created:

Make:	Holden	Model:	Cruze	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2013	<b>Registration:</b>	GRP420	<b>Reg Expiry:</b>	01 Jul 2019	Engine			
WoF Expiry:	08 Feb 2020	Odometer:	120,215 Kms	Good No:	17806039	Oil level	~		
VIN:	6G1PD6EY4DL817816	Next Service:	124000	Service Histor	<b>y:</b> Yes	Smoke & fumes	~		
						Performance	~		
	port is not a warranty a guide only. Conside	eration is made	for age and mileage	. Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	lical inspection prior to	purchase and tr	his can be arranged to	or an additional c	narge.	Coolant condition	~		
	S* W		SD* S*		S PT *	Performance	V		
Key:		=		5(0)-		Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
R = rust	S PT SC W			20	S PT *	Operation	~		
PT = paint defe	ect NP					Noise	~		
C = crack					SC	Clutch			~
P = pin dent	SRPTPSCOR				24116	CV joints	~		
* = decals		10		10	S*	Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
	S W		S* S*	W	S D *	Performance	~		
Body Inst	pection Comments	Note: som	ne defects & blemishes	s may not be disp	layed in the diagram	Hand Brake	~		
						Tyres (lowest observed tread depth of tyres)			
						Left front	4 mm		
						Right front	4	1	mm
						Left rear		5	mm
Conditions During Body Inspection: Dry						Right rear	6 mm		mm
						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension	-		
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
lusterier C						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	driver seat	worn				Head lights	~		
Carpets	Average					Tail lights	~		
						Indicators	~		
Panels	Average					Dashboard warning lights	~		
Dashboa	Average					Wipers (front & rear)	~		
						Window winder FL	~		
Campada						Window winder FR	~		
<u>General Comments</u>					Window winder RL	~			
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	~		
Enging Ti	ming Mochanism	Timina	- Chain			Remote locking	~		
Engine Timing Mechanism: Timing Chain Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)			~
Evidence	ог сапт вен керіас	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: Kyle Mills-Brown Date: 06 May 2019									

I have read and understood this condition guide.

Name: .....

Signature: .....