

Basic Vehicle Condition Guide

Report ID: 17,807,505


Version: 1

Created: 18 Jun 2019

Make: Model: **Body Style:** Toyota Hilux Utility Year: 2015 Registration: JCQ751 Reg Expiry: 26 Aug 2019 WoF Expiry: **Odometer: Good No:** 28 May 2020 81,062 Kms 17807505 VIN: MR0EZ12G104159390 Next Service: 85000 Service History: Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Right fog light cover missing

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

<u>Interior Comments</u>		
Seats	driver seat worn	
Carpets	driver mat holes	
Panels	Average	
Dashboard	Average	

General Comments

Inspected by:

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

John Lindsay

Evidence of Cam Belt Replacement: No

Kms:

Name:

Pass	Fail	N/A		
Engine				
~				
~				
~				
~				
•	•	•		
~				
~				
~				
Transmission				
~				
'				
>				
>				
~				
Brakes				
~				
>				
Tyres (lowest observed tread depth of tyres)				
ä	3	mm		
8		mm		
6		mm		
6		mm		
	Yes			
~				
~				
~				
Air Conditioning / Heater				
~				
Electrical / Accessories				
~				
~				
~				
~				
~				
~				
~				
~				
~				
~				
~				
~				
2	ı			
2				
	ン	マ		

Reversing camera

18 Jun 2019

Signature:

~