

Report ID: 17,807,788 Version: 2 20 Jun 2019 Created:

Make:	Ford	Model:	Mondeo	Body Style:	Wagon		Pass	Fail	N/A
Year:	2015	Registration:	JFG525	Reg Expiry:	07 Oct 2019	Engine			
WoF Expiry:	04 Jul 2020	Odometer:	221,262 Kms	Good No:	17807788	Oil level	~		
VIN:	WF0FXXWPCFFE8212	Next Service:	231520	Service Histor	y: Yes	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and t	his can be arranged fo	or an additional o	narge.	Coolant condition	~		
	S		S D S P		S	Performance	~		
Key:	B	-0	30 3P			Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust D SC W D S D						Operation	~		
PT = paint defe		F		$\left(\left \left(\right) \right\rangle \right)$		Noise	~		
C = crack					R SC	Clutch			~
P = pin dent	HID				7411	CV joints	~		
* = decals	SDSC 91			10	ALC S	Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			1
vv = significan	t scuffs S W		SD S		S P	Performance	~		
Body Incr		Note: son	ne defects & blemishes	may not be disp	played in the diagram	Hand Brake	~		
Body Inspection Comments Chips windscreen						Tyres (lowest observed tread depth of tyres)			2S)
Chips windscreen									mm
						Right front	5.	.0	mm
						Left rear		.0	mm
Conditions During Body Inspection: Dry						Right rear			mm
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	1	l	1
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	stained, dr	iver seat worn				Head lights	~		
	Average					Tail lights	~		<u> </u>
Carpets	Average					Indicators	~		
Panels	left rear do	oor panel scratch	ed			Dashboard warning lights	~		<u> </u>
	A					Wipers (front & rear)	~		
Dashboa	rd Average					Window winder FL	~		
	1				J	Window winder FR	~		<u> </u>
General Comments						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		+
						Number of keys	2		L
Road Conditions During Test Drive: Dry						Central locking	-		~
						Remote locking	~		<u> </u>
Engine Tir	ming Mechanism:	Timing	Chain			Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera			~
							1		
Inspected by: John Lindsay Date: 12 Jun 2019									

I have read and understood this condition guide.

Name:

Signature: