

Report ID: 17,808,306 Version: 1 20 Jun 2019 Created:

Make:	Toyota	Model:	Hilux	Body Style:	Utility		Pass	Fail	N/A
Year:	2012	Registration:		Reg Expiry:	10 Jul 2019	Engine			
WoF Expiry:		Odometer:	198,585 Kms	Good No:	17808306	Oil level	~		1
VIN:	MR0FZ22G001063911			Service Histor		Smoke & fumes	~		
			212000			Performance	~		-
	port is not a warranty					Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition	~		<u> </u>
						Performance			
Key:	SD	-0	SDRPT SDR		S D R PT C	Radiator / Hoses (visual)	ン ン		
S = scratch									
D = dent						Transmission			1
R = rust				10		Operation Noise	~		
PT = paint def	ect			+	D R PT SC	Clutch	~		
C = crack P = pin dent	Ho						~		──
* = decals	DSC DEC				ELA SD	CV joints	~		
SC = stone chips						Wheel bearings	~		
W = significant scuffs S D S D PT S D S D W						Brakes			
		Nata				Performance	~		
	pection Comments	Note: som	ne defects & blemishes	s may not be disp	hayed in the diagram	Hand Brake	<ul> <li></li> </ul>		<u> </u>
Driver door rubs on fender						Tyres (lowest observed tread depth of tyres)			
Right rear fender flare cracked Tailgate light damaged						Left front	5	5	mm
Chip winds						Right front	e		mm
						Left rear	e	5	mm
Conditions During Body Inspection: Dry						Right rear	6	5	mm
Under Corrigge & Under Depart in a stime Community						Spare		Yes	
Under Carriage & Under Bonnet Inspection Comments					Suspension				
Marks on headlining Screw holes in dashboard						Suspension performance	~		
	work in door					Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation	~		
Interior Comments front seats worn						Electrical / Accessories			
Seats	front seats	worn				Head lights	~		
Carpets	Average					Tail lights	~		
Carpets						Indicators	~		
Panels	Average					Dashboard warning lights	2		
Dashboa	rd vent contr	ols loose, left cur	o holder cover missing	]		Wipers (front & rear)	<		
Dashboa	ra			-		Window winder FL	<		
						Window winder FR	~		
<u>General (</u>	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		•
Road Con	ditions During Test	: Drive:	Dry		]	Central locking			~
			•			Remote locking	~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: Y	'es	Kms: 15	2,000	Reversing camera			~
									<u> </u>
Inspected by: John Lindsay Date: 20 Jun 2019									
I have read and understood this condition guide. Name:									