

Report ID: 17,808,766 Version: 2 04 Jul 2019 Created:

Make:	Holden	Model:	Colorado	Body Style:	Utility		Pass	Fail	N/A
Year:	2015	<b>Registration:</b>	JHG651	<b>Reg Expiry:</b>	30 Aug 2019	Engine	•		
WoF Expiry:	03 Jul 2020	Odometer:	116,754 Kms	Good No:	17808766	Oil level	~		
VIN:	MMU148EK0GH61199	Next Service:	123000	Service Histor	<b>y:</b> Yes	Smoke & fumes	~		
						Performance	~		
	port is not a warranty a guide only. Conside	eration is made	for age and mileage	. Parts have not	been dismantled or	Noise	~		
diagnostic tes	sting undertaken. The v	vehicle has beer	driven up to 50km/ł	n from cold. The	Vendor recommends	Cooling System			
a run mechan	ical inspection prior to	purchase and tr	lis can be arranged to	or an additional of	.narge.	Coolant condition	~		
	S		SD SD		S D W	Performance	~		
Key:		=		5(0)-		Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
R = rust	sc w			10	HILS	Operation	~		
PT = paint defe	ect NP					Noise	~		
C = crack				TTY I	R SC	Clutch			~
P = pin dent	RPSC DR				2416	CV joints	~		
* = decals		10		10	E S	Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
	S D	e e	S D S D		S	Performance	~		
Body Insr	pection Comments	Note: som	ne defects & blemishe	s may not be disp	layed in the diagram	Hand Brake	~		
Right rear hubcap missing						Tyres (lowest observed tread depth of tyres)			
Chips windscreen						Left front	8.	.0	mm
						Right front	8.	.0	mm
						Left rear	3.	.0	mm
Conditions During Body Inspection: Dry						Right rear	4.0 n		mm
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
-						Suspension performance	~		
						Steering performance	<		
						Shock absorbers	<		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	front seats	worn				Head lights	~		
Carpote	Average					Tail lights	~		
Carpets						Indicators	~		
Panels	Average					Dashboard warning lights	~		
Dachhar	rd Average					Wipers (front & rear)	<		
Dashboa						Window winder FL	~		
						Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	<		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
	-	<b>-</b>	•			Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
						Data: 37 lun 201			
Inspected by: Kyle Mills-Brown Date: 27 Jun 2019									

I have read and understood this condition guide.

Name: .....

Signature: .....