

Basic Vehicle Condition Guide

Report ID: 17,809,900

Pass

Version: 3

Engine

Oil level

Created: 02 Aug 2019


Fail

N/A

Make: Model: Isuzu D-MAX **Body Style:** Utility Year: 2016 Registration: KFY806 Reg Expiry: 29 Dec 2019 Good No: WoF Expiry: **Odometer:** 24 Jul 2020 41,648 Kms 17809900 VIN: MPATFR85JGT003650 **Next Service:** 48000 Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Small crack windscreen

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Interior Comments			
Seats	stains, driver seat worn		
Carpets	Average		
Panels	Average		
Dashboard	Average		

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Kyle Mills-Brown Inspected by:

Smoke & fumes	~				
Performance	~				
Noise	~				
Cooling System					
Coolant condition	~				
Performance	~				
Radiator / Hoses (visual)	~				
Transmission					
Operation	~				
Noise	~				
Clutch	~				
CV joints	\(\times \)				
Wheel bearings	~				
Brakes					
Performance	~				
Hand Brake	~				
Tyres (lowest observed tread depth of tyres)					
Left front	5	.0	mm		
Right front	3	.0	mm		
Left rear	5	.0	mm		
Right rear	4	.0	mm		
Spare		Yes			
Suspension					
Suspension performance	~				
Steering performance	<i>y y</i>				
Shock absorbers	~				
Air Conditioning / Heater	ļi.		l		
Operation	~				
Electrical / Accessories			l		
Head lights	~				
Tail lights	~				
Indicators	~				
Dashboard warning lights	V				
Wipers (front & rear)					
Window winder FL	✓ ✓				
Window winder FR	·				
Window winder RL	V				
Window winder RR	'				
Rear view mirrors	·				
Radio (basic test only)	~				
CD (basic test only)	· ·				
Number of keys	2	L	<u> </u>		
Central locking			~		
Remote locking	~				
Sat. Nav. (basic test only)	_		V		
Reversing camera	~				
	•				
Date: 10 Jul 2019					

I have read and understood this condition guide.

Name:	