

Basic Vehicle Condition Guide

Report ID: 17,810,776


Version: 1

Created: 24 Jan 2019

Make: Model: **Body Style:** Holden Captiva 5 SUV Year: 2012 Registration: GHN314 Reg Expiry: 01 Jul 2019 WoF Expiry: **Odometer: Good No:** 17 Jan 2020 152,481 Kms 17810776 VIN: KL3DD266JBB147593 Next Service: 162,500 Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Left front bumper needs alignment,

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

| <u>Interior Comments</u> | | | |
|--------------------------|--------------|--|--|
| Seats | minor stains | | |
| Carpets | minor stains | | |
| Panels | Good | | |
| Dashboard | Good | | |

General Comments

Inspected by:

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

| | Pass | Fail | N/A | |
|--|--------------|------|-----|--|
| Engine | | | | |
| Oil level | ~ | | | |
| Smoke & fumes | \(\times \) | | | |
| Performance | ~ | | | |
| Noise | ~ | | | |
| Cooling System | | | | |
| Coolant condition | ~ | | | |
| Performance | ~ | | | |
| Radiator / Hoses (visual) | ~ | | | |
| Transmission | | | | |
| Operation | ~ | | | |
| Noise | V V | | | |
| Clutch | | | ~ | |
| CV joints | ~ | | | |
| Wheel bearings | ~ | | | |
| Brakes | | | | |
| Performance | ~ | | | |
| Hand Brake | ~ | | | |
| Tyres (lowest observed tread depth of tyres) | | | | |
| Left front 3 mr | | | | |
| Right front | : | 3 | mm | |
| Left rear | : | 3 | mm | |
| Right rear | | 5 | mm | |
| Spare | | Yes | | |
| Suspension | | | | |
| Suspension performance | \(\times \) | | | |
| Steering performance | ~ | | | |
| Shock absorbers | ~ | | | |
| Air Conditioning / Heater | | | | |
| Operation 🗸 | | | | |
| Electrical / Accessories | | | | |
| Head lights | ~ | | | |
| Tail lights | | ~ | | |
| Indicators | ~ | | | |
| Dashboard warning lights | ~ | | | |
| Wipers (front & rear) | ~ | | | |
| Window winder FL | ~ | | | |
| Window winder FR | ~ | | | |
| Window winder RL | ~ | | | |
| Window winder RR | ~ | | | |
| Rear view mirrors | ~ | | | |
| Radio (basic test only) | / | | | |
| CD (basic test only) | / | | | |
| Number of keys | 1 | | | |
| Central locking | ~ | | | |
| Remote locking | ~ | | | |
| Sat. Nav. (basic test only) | | | ~ | |
| Reversing camera | | | ~ | |

I have read and understood this condition guide.

Donovan Matara

Name:

Signature:

24 Jan 2019

Date: