

Report ID: 17,811,796 Version: 2 22 Jan 2019 Created:

Make:	Honda	Model:	Odyssey	Body Style:	Wagon		Pass	Fail	N/A
Year:	2006	Registration:	JZE831	Reg Expiry:	14 Jun 2019	Engine			
WoF Expiry:		Odometer:	110,588 Kms	Good No:	17811796	Oil level	~		
VIN:	JHMRB18505C203152	Next Service:	-,	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty		f	Deute have a st	la a constituição de la constituição	Noise	V		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition			
						Performance	~	-	
Key:	L	-0	SW SW		s	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	SC 6/6			TIN	FILL S	Operation	~		
R = rust PT = paint defe				$\left(\left \right\rangle \right)$		Noise	~		
C = crack				+	SC	Clutch	-		~
P = pin dent					세비	CV joints	~		
* = decals	RPSC 916			-NL	ETT PT	Wheel bearings	~		
SC = stone chips						Brakes			
W = significan	t scuffs W S	-	SW SW	JUS	S SC W	Performance	~		
		Note: som	ne defects & blemishes	s may not be disc	laved in the diagram	Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread depth of tyres)			25)
Headlights need attention,scratch marks left wing mirror,									mm
						Right front	5		mm
						Left rear	4		mm
Conditions During Body Inspection: Dry						Right rear		4 mr	
Conditions During Body Inspection: Dry						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Oil leak.	-					Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	wear and t	tear				Head lights	~		
	stains thro	uchout				Tail lights	~		
Carpets		lugnout				Indicators	~		
Panels	boot plast	ic broken,sun vis	or broken.			Dashboard warning lights	~		
						Wipers (front & rear)	~		
Dashboa	rd glove box	Droken.				Window winder FL	~		
						Window winder FR	~		
General Comments					Window winder RL	~			
No coolant,	slight jump between fir	st and second,sli	ght noise under break	king.		Window winder RR	~		
						Rear view mirrors	V		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	· •		
						Remote locking	~		
Engine Tir	ming Mechanism:	Timing (Chain			Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			· ·
						_			
Inspected by: Donovan Matara Date: 22 Jan 2019									

I have read and understood this condition guide.

Name:

Signature: