

Report ID: 17,811,852 Version: 1 12 Feb 2019 Created:

Make:	BMW	Model:	318Ti	Body Style:	Hatchback		Pass	Fail	N/A	
Year:	2003	Registration:	FMA435	Reg Expiry:	28 Jan 2019	Engine				
WoF Expiry:		Odometer:	137,290 Kms	Good No:	17811852	Oil level	~			
VIN:	WBAAU52040KN4560	Next Service:		Service Histor	y: No	Smoke & fumes	~			
					,	Performance	~			
	port is not a warranty		с I II	D		Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System				
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition				
						Performance	~			
Key:	sc	-0	SC		S P SC	Radiator / Hoses (visual)	~			
S = scratch						Transmission				
D = dent	s sc			The	EID S	Operation	~			
R = rust				1 M	JHIH	Noise	~			
PT = paint defe C = crack				+	SC	Clutch	•		~	
P = pin dent	Ho					CV joints	~			
* = decals	s sc pp			AL-		Wheel bearings	~			
SC = stone chips						Brakes				
W = significant scuffs S SC S						Performance	~			
		Note: com				Hand Brake	<i>v</i> <i>v</i>		$\left - \right $	
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram							•			
Minor stone chips in the windscreen ,						Tyres (lowest observed tread depth of tyres)				
						Left front	4		mm	
						Right front	4		mm	
						Left rear	•		mm	
Conditions During Body Inspection: Dry						Right rear	4 mm		mm	
Under Carriage & Under Bonnet Inspection Comments						Spare Yes				
		<u>incernspectic</u>	<u>in comments</u>			Suspension			1	
						Suspension performance	~			
						Steering performance	~		-	
						Shock absorbers	~		<u> </u>	
						Air Conditioning / Heater				
Interior Comments						Operation 🖌				
Average						Electrical / Accessories				
Seats	riveluge					Head lights	~			
Carpets	Average					Tail lights	~			
	doortrim	handlos and mid	dle console need paint	+		Indicators	~			
Panels		nanules and mild	die console need pain	ι,		Dashboard warning lights	~			
Dashboa	rd Average					Wipers (front & rear)	~		<u> </u>	
						Window winder FL	~			
Concret	ommonts					Window winder FR	~			
<u>General Comments</u>					Window winder RL	~		\mid		
						Window winder RR	~		<u> </u>	
						Rear view mirrors	~			
						Radio (basic test only)	~		<u> </u>	
						CD (basic test only)	~			
						Number of keys				
Road Conditions During Test Drive: Dry						Central locking	~			
Engine Timing Mechanisms						Remote locking	~			
Engine Timing Mechanism: Unknown						Sat. Nav. (basic test only)			~	
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~	
Inspected by: Donovan Matara Date: 12 Feb 2019										

Name:

Signature: