

Report ID: 17,811,909 Version: 2 31 Jan 2019 Created:

Make:	Toyota	Model:	Vitz	Body Style:	Hatchback	זך		Pass	Fail	N/A	
Year:	2004	Registration:	JCU592	Reg Expiry:	15 Jul 2019		Engine		1		
WoF Expiry:	12 Sep 2019	Odometer:	180,449 Kms	Good No:	17811909		Oil level	~			
VIN:	7AT0H63EX15046807	Next Service:	175578	Service Histor	y: No		Smoke & fumes	~			
						٦ľ	Performance	~			
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						It	Noise	~			
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends							Cooling System				
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Jŀ	Coolant condition	~			
						٦ŀ	Performance	~			
Key: SSC S SDSC SDSC SDSC							Radiator / Hoses (visual)	~			
S = scratch							Transmission				
D = dent R = rust SSC S S							Operation	~			
PT = paint defect							Noise	~			
C = crack							Clutch			~	
P = pin dent							CV joints	~			
* = decals SC 99							Wheel bearings	~			
SC = stone chips							Brakes	-			
W = significant scuffs S SC S C S C S P SC S D SC S D SC						lŀ	Performance	~			
Noto: como defecto 8 blomichos may not be displayed in the diagram							Hand Brake	· ·			
body inspection comments						ŀ	Tyres (lowest observed tread	-	oftvre	es)	
Mirror casing scratched,RH sill dented ,							Left front 4 mm				
							Right front		+ 4	 mm	
							Left rear			mm	
Conditions During Pody Inspection:						īŀ	Right rear		+ 1	 mm	
Conditions During Body Inspection: Dry						┛┠	Spare Yes				
Under Carriage & Under Bonnet Inspection Comments						٦ŀ,	Suspension				
	-					H	Suspension performance	~			
							Steering performance	• •			
							Shock absorbers	~			
							Air Conditioning / Heater	•			
						<u> </u>	Operation		~		
Interior Comments							Electrical / Accessories		•		
Seats wear and tear,minor stains,worn ,						Ιŀ	Head lights	~			
							Tail lights	v v			
Carpets	drivers flo	or ripped ,					Indicators	~			
Develo	Average							~			
Panels							Dashboard warning lights Wipers (front & rear)	v v			
Dashboa	rd Average						Window winder FL	~			
						┛┠	Window winder FL				
General Comments]	Window winder RL	v			
Slight delay in the idle,slight oil leak from rocker cover ,							Window winder RL	レ レ			
							Rear view mirrors	v v			
							Radio (basic test only) CD (basic test only)	v			
								1			
						╡┟	Number of keys 1				
Road Conditions During Test Drive: Dry						┨┠	Central locking	~			
Engine Timing Mechanism: Timing Chain						٦ŀ	Remote locking			~	
Evidence of Cam Belt Replacement: Not Applicable Kms:							Sat. Nav. (basic test only)			~	
							Reversing camera			~	
Inspected by: Donovan Matara Date: 31 Jan 2019											

I have read and understood this condition guide.

Name:

Signature: