

Basic Vehicle Condition Guide

Report ID: 17,812,216


Version: 1

Created: 05 Feb 2019

Make: Model: Dodge Journey **Body Style:** SUV Year: 2010 Registration: FPE637 Reg Expiry: 15 Mar 2019 **Odometer:** WoF Expiry: 11 Dec 2019 130,676 Kms **Good No:** 17812216 VIN: 3D4P55FD6AT222413 Next Service: 140000 Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Oil seepage lower engine area.

Interior Comments			
Seats	Good		
Carpets	Good		
Panels	Good		
Dashboard	Good		

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Chris Buckley Date: 31 Jan 2019

Name:

	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	V V		
Performance	~		
Noise	~		
Cooling System			
Coolant condition	~		
Performance	~		
Radiator / Hoses (visual)	~		
Transmission			•
Operation	~		
Noise	~		
Clutch			~
CV joints	~		
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	d depth	of tyre	es)
Left front	7	.0	mm
Right front	7.0		mm
Left rear	7.0		mm
Right rear	8.0		mm
Spare	Yes		
Suspension			
Suspension performance	~		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater	1		
Operation	~		
Electrical / Accessories	1		
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	~		
Wipers (front & rear)	~		
Window winder FL	~		
Window winder FR	~		
Window winder RL	~		
Window winder RR	~		
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)	~		
Number of keys	2	l	1
Central locking	~		
Remote locking	~		\dagger
Sat. Nav. (basic test only)			·
Reversing camera			~
-			1

Signature: