

Basic Vehicle Condition Guide

Report ID: 17,812,478


Version: 1

31 Jan 2019 Created:

Make: Model: Hyundai Santa FE **Body Style:** SUV Year: 2015 Registration: JDU403 Reg Expiry: 16 Apr 2019 **Odometer:** Good No: WoF Expiry: 16 Jul 2019 231,691 Kms 17812478 VIN: KMHST81XSFU488638 **Next Service:** 243000 Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Minor stone chips in the windscreen, rear bumper cracked and broken,

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Minor underneath body surface rust,

<u>Interior Comments</u>	
Seats	Average
Carpets	Average
Panels	Average
Dashboard	Average

General Comments

Inspected by:

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Unknown

Evidence of Cam Belt Replacement: Not Applicable Kms:

Name:

Engine Oil level
Smoke & fumes Performance Noise Cooling System Coolant condition Performance Radiator / Hoses (visual) Transmission Operation Noise Clutch CV joints
Cooling System Coolant condition Performance Radiator / Hoses (visual) Transmission Operation Noise Clutch CV joints
Cooling System Coolant condition Performance Radiator / Hoses (visual) Transmission Operation Noise Clutch CV joints
Cooling System Coolant condition Performance Radiator / Hoses (visual) Transmission Operation Noise Clutch CV joints
Coolant condition Performance Radiator / Hoses (visual) Transmission Operation Noise Clutch CV joints
Performance Radiator / Hoses (visual) Transmission Operation Noise Clutch CV joints
Radiator / Hoses (visual) Transmission Operation Noise Clutch CV joints
Transmission Operation Noise Clutch CV joints
Operation Noise Clutch CV joints V
Noise Clutch CV joints
Clutch
CV joints 🗸
·
Wheel bearings 🗸
ı ' ' '
Brakes
Performance 🗸
Hand Brake
Tyres (lowest observed tread depth of tyres)
Left front 3 mm
Right front 3 mm
Left rear 2 mm
Right rear 2 mm
Spare Yes
Suspension
Suspension performance 🗸
Suspension performance Steering performance Shock absorbers
Shock absorbers 🗸
Air Conditioning / Heater
Operation 🗸
Electrical / Accessories
Head lights 🗸
Tail lights 🗸
Tail lights Indicators
Dashboard warning lights 🗸
Wipers (front & rear)
Window winder FL 🗸
Window winder FR 🗸
Window winder RL
Window winder RR
Rear view mirrors
Radio (basic test only)
CD (basic test only)
Number of keys 2
Central locking
Remote locking 🗸
Sat. Nav. (basic test only)
Reversing camera 🗸

31 Jan 2019

Signature:

Date:

Donovan Matara