

Report ID: 17,812,942 Version: 2 29 Jan 2019 Created:

Signature:

| Make: | Mercedes-Benz | Model: | C-Class | Body Style: | Sedan | | Pass | Fail | N/A |
|--|--------------------------|-------------------|------------------------|---------------------------------------|---|--|------|------|----------|
| Year: | 1996 | Registration: | UO4400 | Reg Expiry: | 03 Oct 2019 | Engine | | | |
| WoF Expiry: | 03 Apr 2019 | Odometer: | 261,539 Kms | Good No: | 17812942 | Oil level | ~ | | |
| VIN: | WDB2020282F474544 | Next Service: | | Service History | V: No | Smoke & fumes | ~ | | |
| | | | - | | - | Performance | ~ | | |
| | port is not a warranty | | 6 | Danta harra mat | | Noise | ~ | | |
| This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends | | | | | | Cooling System | | | |
| a full mechan | ical inspection prior to | purchase and th | his can be arranged fo | or an additional c | harge. | Coolant condition | ~ | | 1 |
| | | | | | | Performance | ~ | | - |
| Key: | S SC S | -0 | S P SC S D SC | | S D | Radiator / Hoses (visual) | ~ | | |
| S = scratch | RE | A U | | | The second se | Transmission | | | <u> </u> |
| D = dent | S D SC | | | TIN | S D | Operation | ~ | | 1 |
| R = rust PT = paint defe | | | | $\left(\left \right\rangle \right)$ | | Noise | ~ | | |
| C = crack | | | | + | | Clutch | | | ~ |
| P = pin dent | HIC | | | | 74 <u>11</u> | CV joints | ~ | | |
| * = decals | SDSC 91 | | | -Jul- | ELD SD | Wheel bearings | ~ | | |
| SC = stone chips | | | | | | Brakes | | | 1 |
| W = significan | t scuffs S SC | | S SC S D SC | | S D SC | Performance | ~ | | |
| Podylog | action Commonts | Note: som | ne defects & blemishes | s may not be disp | layed in the diagram | Hand Brake | ~ | | |
| body inspection comments | | | | | | Tyres (lowest observed tread depth of tyres) | | | |
| LR tail light surface cracked ,minor stone chips and small crack in the windscreen ,drivers side A pillar dented ,has a boot spoiler , | | | | | | Left front | 3 mm | | mm |
| | | | | | | Right front | | 3 | mm |
| | | | | | | Left rear | | 3 | mm |
| Conditions During Body Inspection: Dry | | | | | | Right rear | 3 mm | | mm |
| | | | | | | Spare | Yes | | |
| Under Carriage & Under Bonnet Inspection Comments | | | | | | Suspension | | | |
| | | | | | | Suspension performance | ~ | | |
| | | | | | | Steering performance | ~ | | 1 |
| | | | | | | Shock absorbers | ~ | | |
| | | | | | | Air Conditioning / Heater | 1 | | |
| | | | | | | Operation | | | ~ |
| Interior Comments | | | | | | Electrical / Accessories | | | |
| Seats | drivers sea | at ripped,wear an | d tear,stains,worn , | | | Head lights | | ~ | |
| | Average | | | | | Tail lights | | ~ | |
| Carpets | , neuge | | | | | Indicators | ~ | | |
| Panels | hood linin | g coming off esp | ecially around sun roc | of | | Dashboard warning lights | ~ | | |
| | pocket or | lid missing from | under stereo | | | Wipers (front & rear) | ~ | | |
| Dashboa | rd | | | | | Window winder FL | ~ | | |
| | | | | | | Window winder FR | ~ | | |
| <u>General Comments</u> | | | | | | Window winder RL | ~ | | |
| | | | | | | Window winder RR | ~ | | |
| | | | | | | Rear view mirrors | ~ | | |
| | | | | | | Radio (basic test only) | ~ | | |
| | | | | | | CD (basic test only) | ~ | | |
| | | | | | | Number of keys | 1 | • | - |
| Road Con | ditions During Test | t Drive: | Dry | | | Central locking | ~ | | |
| | - | | • | | | Remote locking | | | ~ |
| Engine Timing Mechanism: Unknown Sat. Nav. (basic test only) | | | | | | | | | ~ |
| Evidence | of Cam Belt Replac | ement: N | lot Applicable | Kms: | | Reversing camera | | | ~ |
| Inspected by: Donovan Matara Date: 29 Jan 2019 | | | | | | | | | |

I have read and understood this condition guide.

Name: