

Report ID: 17,814,238 Version: 1 05 Mar 2019 Created:

Make:	Ford	Model:	Mondeo	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2015	<b>Registration:</b>	LUM997	<b>Reg Expiry:</b>	08 Apr 2019	Engine	•		•
WoF Expiry:	19 Feb 2020	Odometer:	145,066 Kms	Good No:	17814238	Oil level	~		
VIN:	WF0EXXWPCEFK8545	Next Service:	155000	Service Histor	<b>y:</b> No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty a guide only. Conside	eration is made	for age and mileage	e. Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and ti	his can be arranged f	or an additional o	inarge.	Coolant condition	~		
						Performance	~		
Key:		=		5(0)-		Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
						Operation	~		
PT = paint def	ect NP					Noise	~		
C = crack						Clutch			~
P = pin dent	HP				2416	CV joints	~		
* = decals						Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
						Performance	~		
Body Insr	pection Comments	Note: son	ne defects & blemishe	s may not be disp	blayed in the diagram	Hand Brake	~		
Minor stone chips in the windscreen ,LH sill dented and scratches ,						Tyres (lowest observed tread depth of tyres)			
millor stone emps in the windsereen jer sin dented and seddenes ;					Left front 2 m			mm	
						Right front		2	mm
						Left rear		3	mm
Conditions During Body Inspection: Dry						Right rear		3	mm
						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	Good					Dashboard warning lights	~		
	, Good					Wipers (front & rear)	~		
Dashboa	rd Good					Window winder FL	~		
	I					Window winder FR	~	-	
General C	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2	L	I
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)	V		
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera	~		
									1
Inspected by: Donovan Matara Date: 05 Mar 2019									

I have read and understood this condition guide.

Name: .....

Signature: .....