

Report ID: 17,814,293 Version: 1 25 Feb 2019 Created:

Make:	BMW	Model:	3 Series	Body Style:	Sedan		Pass	Fail	N/A
Year:	2004	Registration:	CCR525	Reg Expiry:	01 Apr 2019	Engine	1	I	1
WoF Expiry:		Odometer:	166,663 Kms	Good No:	17814293	Oil level	~		
VIN:	WBAAZ12060NH5732	Next Service:	176600	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for ago and miloago	Parts have not	been dismonthed or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition	~		
	S P SC				S SC	Performance	~		
Key:	SPSC	-0	S SC S SC	-01-	- SSC	Radiator / Hoses (visual)	r		
S = scratch						Transmission			
D = dent R = rust	s c sc			715		Operation	V		
PT = paint defe		F		$\left[\left(\right) \right]$		Noise	r		
C = crack					SC	Clutch			r
P = pin dent	ssc dP				74116	CV joints	~		
* = decals				To .		Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			I
vv = significan	S P SC		S P SC S P	S	S SC	Performance	~		
Body Insr	pection Comments	Note: son	ne defects & blemishes	may not be disp	blayed in the diagram	Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread depth of tyres)			
						Left front	6 mm		mm
						Right front		5	mm
						Left rear		3 mm	
Conditions During Body Inspection: Dry Right rear							3 mm		
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
Shock absorbers							~		
Air Conditioning							•		•
Operation								~	
Interior Comments						Electrical / Accessories			
Seats	wear and t	ear,				Head lights	~		
	Average					Tail lights	~		
Carpets						Indicators	~		
Panels	Average					Dashboard warning lights	~		
Deckler	rd Average					Wipers (front & rear)	~		
Dashboa	iu j					Window winder FL	~		
	-					Window winder FR	~		
<u>General Comments</u>						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry							~		
Engine Timing Mechanism: Unknown Sat Nav (basic test on							~		
-	Sat. Nav. (basic test only)			~					
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: Donovan Matara Date: 25 Feb 2019									

I have read and understood this condition guide.

Name:

Signature: