

Report ID: 17,814,582 Version: б 23 May 2019 Created:

Signature: .....

Make:	Toyota	Model:	Landcruiser Prado	Body Style:	SUV		Pass	Fail	N/A	
Year:	2015	<b>Registration:</b>	JBS882	<b>Reg Expiry:</b>	07 Nov 2019	Engine				
WoF Expiry:	08 Mar 2020	Odometer:	171,471 Kms	Good No:	17814582	Oil level	~			
VIN:	JTEBH3FJ90K166486	Next Service:	184000	Service Histor	<b>y:</b> Yes	Smoke & fumes	V			
						Performance	~			
	port is not a warranty a guide only. Conside	eration is made	for age and mileage	. Parts have not	been dismantled or	Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System				
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	or an additional of	charge.	Coolant condition	~			
			S D		SC	Performance	~			
Key:		-0		5(0)-		Radiator / Hoses (visual)	~			
S = scratch D = dent						Transmission				
R = rust	SDCSC			710		Operation	~			
PT = paint defe	ect NP					Noise	V			
C = crack						Clutch			~	
P = pin dent	s de				2414	CV joints	V			
"= decais						Wheel bearings	~			
SC = stone chips W = significant scuffs						Brakes				
	S SC		SC SC			Performance	~			
Body Insr	pection Comments	Note: som	ne defects & blemishes	s may not be disp	blayed in the diagram	Hand Brake	~			
1 remote key fail					Tyres (lowest observed tread depth of tyres)					
					Left front	1	0	mm		
						Right front	1	0	mm	
						Left rear	1	0	mm	
Conditions During Body Inspection: Dry						Right rear	10 mm		mm	
						Spare	Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension				
AWD						Suspension performance	~			
						Steering performance	~			
						Shock absorbers	~			
						Air Conditioning / Heater	•			
						Operation	~			
Interior Comments						Electrical / Accessories				
Seats	Average					Head lights	~			
Correcto	Good					Tail lights	~			
Carpets						Indicators	~			
Panels	Average					Dashboard warning lights	~			
Dashboa	rd Good					Wipers (front & rear)	~			
	iu					Window winder FL	~			
	_					Window winder FR	~			
General C	<u>Comments</u>					Window winder RL	~			
						Window winder RR	~			
						Rear view mirrors	~			
						Radio (basic test only)	~			
						CD (basic test only)	~			
						Number of keys	2			
Road Conditions During Test Drive: Dry										
			_			Remote locking	~			
Engine Timing Mechanism: Cambelt Sat. Nav. (basic test only)									~	
Evidence	of Cam Belt Replac	ement: Y	es	Kms: 15	54,520	Reversing camera	~			
Inspector	Inspected by: Ca Thach Date: 23 May 2019									
Thispected by, Cu much Date, 23 May 2019										

I have read and understood this condition guide.

Name: .....