

Report ID: 17,814,927 Version: 1 04 Mar 2019 Created:

Make:	Ford	Model:	Focus	Body Style:	Hatchback			Pass	Fail	N/A	
Year:	2013	Registration:	GWS545	Reg Expiry:	31 May 2019	Engine					
WoF Expiry:	26 Feb 2020	Odometer:	73,779 Kms	Good No: 17814927		Oil level		~			
VIN:	MPB1XXMXB1DJ2580	Next Service:	83800	Service Histor	y: No	Smoke & f	umes	~			
						Performan	nce	~			
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise		~			
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System					
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant co	ondition	~			
	S SC		P SC P SC	S	S SC	Performan	nce	~			
Key: S = scratch		=(0)		5(0)-		Radiator /	Hoses (visual)	~			
						Transmissi	on				
R = rust SSC AR						Operation	Operation				
PT = paint defe	ect NP					Noise		~			
C = crack				\square		Clutch				~	
P = pin dent	ssc dk				~HILLS	CV joints		~			
* = decals SC = stone chips						Wheel bearings					
W = significant scuffs						Brakes					
		\sim	S D SC			Performan	nce	~			
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brak	Hand Brake				
						Tyres (lowest observed tread depth of tyres)					
						Left front	Left front		7 mm		
						Right front		7 mm		mm	
						Left rear		7 mm		mm	
Conditions During Body Inspection: Dry						Right rear	Right rear		7 mm		
						Spare Yes			Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension					
						· · · · · · · · · · · · · · · · · · ·	n performance	~			
						Steering p	erformance	~			
						Shock absorbers 🖌					
						Air Conditioning / Heater					
Interior Commonts						Operation 🖌					
Interior Comments Good						Electrical / Accessories					
Seats						Head light	ts	~			
Carpets	Good					Tail lights		~			
	Good					Indicators		~			
Panels	Good						d warning lights	~			
Dashboa	rd Good					Wipers (fro		~			
						Window w		~			
Concrol	Comments					Window w		~			
						Window w		~			
						Window w		~			
						Rear view		~			
							sic test only)	~			
						CD (basic test only)		~			
							Number of keys 1				
Road Conditions During Test Drive: Dry						Central loo	-	~			
- Engine Ti	ming Mechanism	Unknow	(n			Remote lo	-	~			
						Sat. Nav. (basic test only)				~	
Evidence	ог сант вен керіас	ement: N	lot Applicable	Kms:		Reversing	camera			~	
Inspected by: Donovan Matara Date: 04 Mar 2019											

I have read and understood this condition guide.

Name:

Signature: