

Report ID: 17,815,260 Version: 2 08 Mar 2019 Created:

Make:	Honda	Model:	Civic	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2004	Registration:	HFW440	Reg Expiry:	19 Jul 2019	Engine			
WoF Expiry:	28 Feb 2020	Odometer:	152,599 Kms	Good No:	17815260	Oil level	~		
VIN:	7AT08G0WX13402552	Next Service:	162500	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty		for one and miles as	Dauta hava nat	heen discontined or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and t	nis can be arranged fo	r an additional c	harge.	Coolant condition	~		
						Performance	~		
Key:	S SC S	-0	S P SC S P SC		S P SC	Radiator / Hoses (visual)	~		
S = scratch							Transmission		
D = dent	SDCSC			The	E SC	Operation	~		
R = rust PT = paint defe				\int	JHIH	Noise	~		
C = crack				+	SC	Clutch			~
P = pin dent	Ho					CV joints	~		•
* = decals	s PIK			The	ELIP SD	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs S D SC S S D S D S D S D S D S C S D S C S D S C D S D S						Performance	~		
		Note: son	e defects & blemisbes	may not be disp		Hand Brake	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram							•	oftyre))
LH sill dented and scratched ,						Tyres (lowest observed tread depth of tyres) Left front 3 mm			
						Right front			mm
						Left rear		3	mm
								2	mm
Conditions During Body Inspection: Dry						Right rear 2 mm			mm
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
	indge a onder bor	meenspeede	<u>eonnents</u>			Suspension			-
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	-		-
Interior Comments						Operation		~	
Average						Electrical / Accessories			
Seats						Head lights	~		
Carpets	Average					Tail lights	~		
	Average					Indicators	~		
Panels	/ Weidge					Dashboard warning lights	~		
Dashboa	rd fan contro	ols not working o	n dashboard ,			Wipers (front & rear)	~		
						Window winder FL	~		
Ganaral	Comments					Window winder FR	~		
						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	~		
Engine Ti	ming Machanism	Comboli	-			Remote locking	~		
Engine Timing Mechanism: Cambelt Evidence of Cam Belt Replacement: Yes Kms: 116,035						Sat. Nav. (basic test only)			~
Evidence	oi Cam Beit Replac	ement: Y	es	Kms: 11	6,035	Reversing camera			~
Inspected by: Donovan Matara Date: 08 Mar 2019									

I have read and understood this condition guide.

Name:

Signature: