

Report ID: 17,815,447 Version: 1 11 Jul 2019 Created:

Make:	BMW	Model:	1 Series	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2011	<b>Registration:</b>	FUB902	<b>Reg Expiry:</b>	01 Jul 2019	Engine			
WoF Expiry:	10 Jul 2020	Odometer:	167,387 Kms	Good No:	17815447	Oil level	~		
VIN:	WBAUH12020E12447(	Next Service:	182400	Service Histor	<b>/:</b> No	Smoke & fumes	~		
						Performance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	~		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition	V		
						Performance	~		
Key:	S SC	-0	S P SC S P SC	$-\alpha$		Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent B = rust SSC SSC SSC						Operation	~		
R = rust PT = paint defect						Noise	~		
C = crack						Clutch			~
P = pin dent						CV joints	~		
* = decals SC 999 S						Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs S SC S SC S SC S SC						Performance	~		
Deduction		Note: son	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Body inspection comments						Tyres (lowest observed tread	d depth	of tyre	L es)
Minor stone chips in the windscreen ,									mm
						Right front		5	mm
						Left rear		5	mm
Condition	as During Pady Inc	action	Dmi			Right rear		5	mm
Conditions During Body Inspection: Dry						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	-		L
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats Good						Head lights	~		
	Card					Tail lights	~		
Carpets	Good					Indicators	~		
Panels	Good					Dashboard warning lights	~		
						Wipers (front & rear)	~		
Dashboa	rd Good					Window winder FL	~		
						Window winder FR	~		
General Comments						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		L
Road Conditions During Test Drive: Dry						Central locking			
Road Conditions During Test Drive: Dry						Remote locking	~		
Engine Timing Mechanism: Unknown						Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera			~
L	-								
Inspected by: Donovan Matara Date: 11 Jul 2019									

I have read and understood this condition guide.

Name: .....

Signature: .....