

 Report ID:
 17,817,038

 Version:
 1

 Created:
 07 Aug 2019

Make:	Mitsubishi	Model:	Triton	Body Style:	Utility		Pass	Fail	N/A
Year:	2013	Registration:	GZF621	Reg Expiry:	16 Aug 2019	Engine			·
WoF Expiry:	15 Jul 2020	Odometer:	275,359 Kms	Good No:	17817038	Oil level	~		
VIN:	MMAJYKB40DD00991	Next Service:	282000	Service Histor	r y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty a quide only. Conside	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	lical inspection prior to	purchase and t	his can be arranged fo	or an additional	charge.	Coolant condition	~		
	S SC		S P SC S P		S D SC	Performance	~		
Key:		-0		5(0)-	3030	Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			1
D = dent R = rust PT = paint defect C = crack						Operation	~		
						Noise	~		
						Clutch			~
P = pin dent						CV joints	~		
*= decais						Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
W = significant sculls S SC SSC SSC SPSC						Performance	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake	~		
Minor stone chips in the windscreen, RR guard reflector light broken , both side sill steps have surface rust ,						Tyres (lowest observed tread depth of tyres)			
						Left front	Left front 3		
						Right front	3	3	mm
						Left rear	e	5	mm
Conditions During Body Inspection: Wet						Right rear	6	5	mm
						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Underneath	n body surface rust ,					Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
		Air Conditioning / Heater	•						
						Operation	~		
Interior Comments drivers seat ripped, wear and tear,						Electrical / Accessories			
Seats	drivers sea	it ripped,wear ar	id tear ,			Head lights	~		
Carpote	wear and t	tear ,				Tail lights	~		
Carpets						Indicators	۲		
Panels	Average					Dashboard warning lights	2		
Dashboa	Average					Wipers (front & rear)	~		
						Window winder FL	~		
						Window winder FR	~		
<u>General Comments</u>						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		<u> </u>
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Wet						Central locking	~		<u> </u>
Engine Timing Mechanism: Cambelt						Remote locking	~		<u> </u>
Evidence of Cam Belt Replacement: No Kms:						Sat. Nav. (basic test only)			~
Evidence	Reversing camera			~					
Inspected	d by: Donovan Matar	а				Date: 07 Aug 20	19		

I have read and understood this condition guide.

Name:

Signature: