

Report ID: 17,817,784 Version: 1 Created: 04 Sep 2019

Make:	Suzuki	Model:	Swift	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2006	<b>Registration:</b>	KGM909	<b>Reg Expiry:</b>	18 Jul 2019	Engine			
WoF Expiry:	12 Mar 2020	Odometer:	127,594 Kms	Good No:	17817784	Oil level	~		
VIN:	7AT0GK0CX16155976	Next Service:	137800	Service Histor	<b>y:</b> No	Smoke & fumes	V		
						Performance	r		
	port is not a warranty a guide only. Conside	eration is made	for age and mileage	. Parts have not	been dismantled or	Noise	V		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	or an additional o	charge.	Coolant condition	~		
	S P SC S		S SC S P SC		S SC	Performance	~		
Key:	3530 [3	-0	33C 3F3C	500-	33	Radiator / Hoses (visual)	~		
S = scratch D = dent R = rust PT = paint defect C = crack P = pin dent S D SC S D SC						Transmission			
						Operation	~		
						Noise	~		
						Clutch			~
						CV joints	~		
* = decals S D SC 9 9 S S P SC						Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs S D SC S S D SC S S D C SC S S D C SC						Performance	~		
Deduction		Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
body inspection comments						Tyres (lowest observed tread	d depth	of tyre	es)
Minor stone chips in the windscreen ,								mm	
						Right front		3	mm
						Left rear		3	mm
Conditions During Pody Inspection: Wet						Right rear			mm
Conditions During Body Inspection: Wet						Spare			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	•		
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats Average						Head lights	~		
						Tail lights	~		
Carpets	Average					Indicators	~		
Panels	Average					Dashboard warning lights	~		
						Wipers (front & rear)	~		
Dashboa	rd Average					Window winder FL	~		
						Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Wet						Central locking			
Koad Con	allions During Test	Drive:	Wet			Remote locking	-	~	
Engine Tir	ming Mechanism:	Timing (	Chain			Sat. Nav. (basic test only)		-	~
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera			
									~
Inspected by: Donovan Matara Date: 04 Sep 2019									

I have read and understood this condition guide.

Name: .....

Signature: .....