

Basic Vehicle Condition Guide

Report ID: 17,817,946


Version: 1

Created: 15 Aug 2019

Make: Model: Chrysler 300 **Body Style:** Sedan Year: 2016 Registration: JRH873 Reg Expiry: 14 Sep 2019 WoF Expiry: **Odometer: Good No:** 29 Mar 2020 52,175 Kms 17817946 VIN: 2C3CCAYG8FH909138 Next Service: 0 Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Note: some defects & blemishes may not be displayed in the diagram

Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

<u>Interior Comments</u>			
Seats	Good		
Carpets	Good		
Panels	Good		
Dashboard	Good		

General Comments

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Unknown

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Donovan Matara

Engine	Pass	Fail	N/A		
<u> </u>			1		
	Engine				
Oil level	~				
Smoke & fumes	~				
Performance	VV				
Noise	~				
Cooling System					
Coolant condition	~				
Performance	V				
Radiator / Hoses (visual)	~				
Transmission					
Operation	~				
Noise	ν ν				
Clutch			~		
CV joints	~				
Wheel bearings	~				
Brakes					
Performance	_				
Hand Brake	<u> </u>				
Tyres (lowest observed tread	depth	of tyre	,e) 		
Left front 3 mm					
Right front			mm		
Left rear	4		mm		
Right rear		* 1	mm		
Spare		-			
Spare Yes Suspension					
Suspension performance					
Steering performance	~				
Shock absorbers	V V				
Air Conditioning / Heater					
Operation Electrical / Accessories					
Head lights	·/				
Tail lights	<u>, </u>				
Indicators	ν ν				
Dashboard warning lights	<u> </u>				
Wipers (front & rear)	~				
Window winder FL	~				
Window winder FR	~				
Window winder RL	~				
Window winder RR					
Rear view mirrors	<i>v</i>				
Radio (basic test only)	<u> </u>				
CD (basic test only)	<u> </u>				
Number of keys					
·	2				
Central locking	<i>V</i>				
Remote locking	<u>/</u>				
Sat. Nav. (basic test only) Reversing camera	٧ ٧				
neversing camera					

I have read and understood this condition guide.

Name:

Signature:

15 Aug 2019

Date: