

Report ID: 17,818,291 Version: 1 22 Aug 2019 Created:

Make:	lsuzu	Model:	MU-X	Body Style:	SUV		Pass	Fail	N/A
Year:	2016	Registration:		Reg Expiry:	09 Nov 2019	Engine	I		L
WoF Expiry:		Odometer:	148,713 Kms	Good No:	17818291	Oil level	~		
VIN:	MPAUCS85GFT00895(Next Service:	152000	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty		C 1 1	D		Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition			
						Performance	~		
Key:	S SC	-0	S D SC S D SC		S D SC	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent SDCSC SC						Operation 🖌			
R = rust PT = paint defe				\int	THIA	Noise	~		
C = crack					SC	Clutch	•		~
P = pin dent						CV joints	~		•
* = decals	s sc pip			AL.	ELIPE IS	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs S SC S D SC S D SC S D SC						Performance			
		Note: som	e defects & blemishes	may not be disr		Hand Brake	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram							•		
Minor stone chips in the windscreen ,						Tyres (lowest observed tread depth of tyres) Left front 7 mm			mm
						Right front		7	
						Left rear		7	mm
							7 mm		
Conditions During Body Inspection: Wet						Right rear	7 mm		
Under Carriage & Under Bonnet Inspection Comments						Spare Suspension	Yes		
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	-		
							~		
						Air Conditioning / Heater			
Interior Comments						Operation 🖌			
	Average					Head lights			
Seats							~		
Carpets	Average					Tail lights	~		
	Average					Indicators	~		
Panels						Dashboard warning lights	~		
Dashboa	rd Average					Wipers (front & rear)	~		
						Window winder FL	~		
General Comments						Window winder FR	~		
	<u></u>					Window winder RL	 		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Wet						Central locking	~		
Engine Tir	ming Mechanism:	Timing				Remote locking	~		
Engine Timing Mechanism: Timing Chain Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)	~		
		cilient. N		11115.		Reversing camera	~		
Inspected by: Donovan Matara Date: 22 Aug 2019									

I have read and understood this condition guide.

Name:

Signature: