

Next Service:

doou n	0.	170	105
Service	History		No

Service History:

Note: This report is not a warranty

JM0GY103200304802

VIN:

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends Cooling System a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

298088

Performance S SC S P SC SDSC S SC Key: Radiator / Hoses (visual) S = scratch **Fransmission** D = dent S S SC Operation R = rustNoise PT = paint defect SC C = crackClutch P = pin dent CV joints S SC * = decals SD Wheel bearings SC = stone chips Brakes W = significant scuffs S SC S P SC S P SC SP Performance Note: some defects & blemishes may not be displayed in the diagram Hand Brake **Body Inspection Comments** Tyres (lowest observed tread depth of tyres) Minor stone chips in the windscreen , Left front **Right front** Left rear **Right rear** Conditions During Body Inspection: Wet Spare Under Carriage & Under Bonnet Inspection Comments Suspension Suspension performance Steering performance Shock absorbers

			Air Conditioning / Heater			
_			Operation		~	
Interior Comments		Electrical / Accessories				
Seats	Average		Head lights	~		
Correcto	Average		Tail lights	~		
Carpets			Indicators	~		
Panels	Average		Dashboard warning lights	~		
Average	Average		Wipers (front & rear)	~		
Dashboard			Window winder FL	~		
			Window winder FR	~		
<u>General Comm</u>	<u>ients</u>		Window winder RL	~		
			Window winder RR	~		
			Rear view mirrors	~		
			Radio (basic test only)	~		
			CD (basic test only)	~		
			Number of keys	1		
Road Conditions During Test Drive: Wet			Central locking	~		
			Remote locking	~		
Engine Timing Mechanism: Timing Chain		Sat. Nav. (basic test only)			~	
Evidence of Car	m Belt Replacement: Not Applicable Kms:		Reversing camera			~
Inspected by:	Donovan Matara		Date: 22 Aug 20	19		

I have read and understood this condition guide.

Name:

Signature:

Report ID: 17,818,546 Version: 1

Created: 22 Aug 2019

Fail

N/A

V

mm

mm

mm

mm

Pass

V

V

V

V

V V

V

V

V

V

V

~

~

7

7

7

7

V

V

~

Yes

Engine

Oil level

Noise

Smoke & fumes

Coolant condition

Performance