

Report ID: 17,818,682 Version: 2 08 Nov 2019 Created:

Make:	Mitsubishi	Model:	Outlander	Body Style:	SUV		Pass	Fail	N/A
Year:	2014	Registration:	HPE946	Reg Expiry:	29 Apr 2020	Engine	1		
WoF Expiry:	16 Sep 2020	Odometer:	90,656 Kms	Good No:	17818682	Oil level	~		
VIN:	JMFXDGG2WEZ00123	Next Service:	95,000	Service Histor	y: Yes	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for age and mileage	Parts have not	been dismontled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition	~		
						Performance	~		
Key:	L	-0	S SC W W	$-\alpha$	SC	Radiator / Hoses (visual)	~		
S = scratch						Transmission			L
D = dent R = rust	sw dla			The	SW	Operation	~		
PT = paint defe				$\left[\right] \left[\right]$		Noise	~		
C = crack					SC	Clutch			~
P = pin dent	110				세비	CV joints	~		
* = decals	RSC 919			The	SRP SRP	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant	t scuffs W S		RWW	JUS	SC	Performance	~		
Dealerteen		Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
body inspection comments						Tyres (lowest observed tread depth of tyres)			es)
Stone chips in the windscreen,									mm
						Right front	6.	-	mm
						Left rear	6.		mm
Conditions During Body Inspection: Dry						Right rear			mm
Conditions During Body Inspection: Dry						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	rips in pas	sengers seat				Head lights	~		
	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	Good					Dashboard warning lights	~		
	Good					Wipers (front & rear)	~		
Dashboa	rd Good					Window winder FL	~		
	1					Window winder FR	~		
General Comments					Window winder RL	~			
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		++
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		\square
,						Remote locking	~		
Engine Tir	ming Mechanism:	Timing (Chain			Sat. Nav. (basic test only)	~		
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera	 ✓ 		
Inspected by: Donovan Matara Date: 02 Oct 2019									

I have read and understood this condition guide.

Name:

Signature: