

Report ID: 17,818,902 Version: 1 Created: 04 Sep 2019

Make:	Honda	Model:	Civic	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2005	<b>Registration:</b>	HQP995	Reg Expiry:	17 Sep 2019	Engine	1	I	L
WoF Expiry:	27 Aug 2020	Odometer:	139,471 Kms	Good No:	17818902	Oil level	~		
VIN:	7AT08G0WX14403009	Next Service:	0	Service Histor	V: No	Smoke & fumes	~		<u> </u>
						Performance	~		
	port is not a warranty	aration is made	for ago and milaago	Parts have not	been dismonthed or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	nis can be arranged fo	or an additional c	harge.	Coolant condition	~		
	S SC				S	Performance	~		
Key:	L SSC L	-0	S SC S P SC			Radiator / Hoses (visual)	V		
S = scratch						Transmission			1
D = dent R = rust	s sc			715	HILS	Operation	~		
PT = paint defe		F		$\left( \left  \left( \right) \right\rangle \right)$		Noise	~		
C = crack					S SC	Clutch			~
P = pin dent	HID				74 <u>11</u> 4	CV joints	~		
* = decals	ssc 916			- Jul	ALC'S	Wheel bearings	~		
SC = stone chips						Brakes			L
W = significan	t scuffs S SC	$\neg \varnothing$	S SC S SC		S SC	Performance	~		
Podulac		Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Body Inspection Comments Minor stone shins in the winderscon						Tyres (lowest observed tread	erved tread depth of tyres)		
Minor stone chips in the windscreen ,						Left front 3 mm			
						Right front		3	mm
						Left rear		5	mm
Conditions During Body Inspection: Wet						Right rear	5 mm		mm
Conditions During Body Inspection. Wet						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		<u> </u>
						Air Conditioning / Heater			1
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
	Average					Tail lights	~		
Carpets	Average					Indicators	~		+
Panels	Average					Dashboard warning lights	~		<u> </u>
	A					Wipers (front & rear)	~		+
Dashboa	rd Average					Window winder FL	~		<u> </u>
	1					Window winder FR	~		<u> </u>
<u>General</u> C	<u>Comments</u>					Window winder RL	~		$\mathbf{t}$
						Window winder RR	~		<u> </u>
						Rear view mirrors	~		1
						Radio (basic test only)	~		<u> </u>
						CD (basic test only)	~		
						Number of keys	2	I	L
Road Con	ditions During Test	t Drive:	Wet			Central locking	~		
	-					Remote locking	~		1
Engine Tir	ming Mechanism:	Unknow	'n			Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
							1	1	
Inspected	d by: Donovan Matar	а				Date: 04 Sep 20	19		

I have read and understood this condition guide.

Name: .....

Signature: .....